

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-1511	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator ARCO Oil and Gas Company Division of Atlantic Richfield Company		8. Farm or Lease Name State "F" DE	
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 4	
4. Location of Well UNIT LETTER M 330 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 19 TOWNSHIP 21S RANGE 36E NMPM.		10. Field and Pool, or Wildcat Eumont Queen Gas	
15. Elevation (Show whether DF, RT, GR, etc.) 3636'		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Retrieve BP, CO hole <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up, kill well, install BOP, POH w/compl assy.
2. Retrieve BP @ 3847'.
3. CO sd to 3901' PBD. Swab test. Run compl assy.
4. Return all Eumont Gas perms 3343-3787' & 3858-3868' to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Walter P. Lawrence TITLE Drlg. Engr. DATE 7/13/82

ORIGINAL SIGNED BY

JERRY SEXTON
DISTRICT 1 SUPR.

APPROVED BY _____ TITLE _____ DATE JUL 16 1982

CONDITIONS OF APPROVAL, IF ANY: