

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
176

SUNDARY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator ARCO Oil & Gas Company Division of Atlantic Richfield Company	8. Farm or Lease Name State 176
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240	9. Well No. 2
4. Location of Well UNIT LETTER <u>0</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>19</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Eumont Yates 7 R Qn
15. Elevation (Show whether DF, RT, GR, etc.) 3667' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to P & A in the following manner:

1. Rig up, install BOP, POH w/ comp assy.
2. Run CBL 3880' to surf. RIH w/ CIBP, set BP @ 3850'. Dump 35' C1 "C" cmt on top.
3. Perforate 6-5/8" csg above TOC as indicated by CBL. Break circ thru perfs to surf.
4. RIH w/ cmt retr, set above perfs. Pump thru perfs w/ C1 "C" cmt cont'g 2% CaCl₂, 4% gel & circ to surf. Spot 35' cmt on top of retr.
5. Spot 100' cmt plug 1600-1700'. Spot heavy gelled mud between all cmt plugs.
6. Spot 10 sx cmt plug @ surface. Install regulation dry hole marker @ surf. Clean & level location.

THE COMPLETION MUST BE NOTICED 24
HOURS AFTER THE ESTIMATED
DATE OF COMPLETION FOR THE CLOS
TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Dist. Drlg. Supt. DATE 8/11/80

Orig. Signed By

Jerry Sexton

Dist. L. Supt.

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

AUG 15 1980