

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
176

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Atlantic Richfield Company	State 176
3. Address of Operator	9. Well No.
P. O. Box 1710, Hobbs, New Mexico 88240	2
4. Location of Well	10. Field and Pool, or Whichever
UNIT LETTER 0 330 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 19 TOWNSHIP 21 RANGE 36E NMPM.	Eumont Yates 7 Rvrs. On
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3667' GR	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3975'. Presently completed in Eumont Yates 7 Rivers Queen OH interval 3880-3975'. Well has been shut in since 5/1/65. Uneconomical to produce.

15-1/2" csg set @ 240'. Cmtd w/300 sx.
9" OD csg set @ 1534'. Cmtd w/600 sx.
6-5/8" OD csg set @ 3880'. Cmtd w/400 sx. Top of salt @ 1577'

Propose to P&A in the following manner:

1. Rig up install BOP. POH w/completion assembly.
2. Set cement retainer @ 3650.
3. Squeeze open hole with 100 sx cement.
4. Perf 4 holes 6-5/8" csg @ 1550'. Fill hole with mud between all plugs.
5. Set cmt retr @ 1400'. Attempt to circ cmt to surf between 6-5/8" & 9".
6. Spot 10 sx, plug @ surf.
7. Clean & level location. Install marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Runyan TITLE Dist. Drlg. Supt. DATE 2/27/79

APPROVED BY John Runyan TITLE Geologist DATE 3/1/79

CONDITIONS OF APPROVAL, IF ANY:

Expires 9/5/79