NO. OF COPIES RECEIVED		
DISTRIBUTION		Form C+193 Supersedes Olf
SANTA FE	NEW HEXICO.OUL CONSERVATION POWAL	C-102 and C-103
FILE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.	- 12:0	
LAND OFFICE	UEP 1 10 17 14 289	5c. Indicate Type of Leave
OPERATOR		Si Ka . Fee
		5. State Cill & Gas. Lease No.
	·	B-452
(DO NOT USE THIS FORM FOR F	DRY NOTICES AND REPORTS ON WELLS PROPORALS TO BRILL OR TO DEEPER OR FLUG FACK TO A DIFFERENT RESERVOID. ATION FOR PERMIT (FORM C-101) FOR SUCH PROPORALS.)	37777777777777777777777777777777777777
USE "APPLIC	ATION FOR PERMIT -** (FORM C-101) FOR SUCH PROPOBALS.)	
OIL GAS WELL		7. Unit Agreement Name
2. Name of Operator	OTHER-	
	8, Farm or Lease Nome	
Atlantic Rich 3. Address of Operator	State "D"	
	8, Roswell, New Mexico 89201	9. Well No.
	O, NOSWEII, NEW MEXICO 59201	1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER	1980 FEET FROM THE East LINE AND 1980 FEET	Eumont-Grayburg
THE South LINE, SECT	TION 20 TOWNSHIP 21-S FANGE 36-E	
And the Contraction of the standard and a standard and and and and and and and and and an	**************************************	
A 11 15. Elevation (Show whether DF, RT, GR, etc.)		12. County
	3624' DF	Lea ())))))))
16. Check	Appropriate Box To Indicate Nature of Notice, Report o	
NOTICE OF		
	SUBSEQU	JENT REPORT OF:
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
PULL OR ALTER CASING	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
THE ON ACIER CADING	CHANGE PLANS CASING TEST AND CEMENT JOB]
OTHER	OTHER	
0)nck		
17, Describe Proposed or Completed (Dependions (Clearly state all pertinent dataile and size and size	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

First quarter of 1969 production from this well averaged 4 BOPD plus 90% water. A plugback and acid job in May, 1969 failed and well is producing 100% water. No other remedial possibilities exist. We propose to plug and abandon by setting a cast iron bridge plug at approximately 3810' and capping same w/10 sx of cement. 10 sx of cement to be placed in top of well and regulation dry hole marker erected. Location will be cleared and levelled. All casing strings will remain intact. Work will start about 10/1/69.

Use mud

16. I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNED Charges	Dist. Drlg. Supervisor	DATE 9-26-69		
APPROVED BY	JDPhervice Contraction Contraction	DATE SEP 20 1000		