Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION D

NTTITCTANI		
DIVISION	WELL API NO.	
4-2088	300250472000	
	5. Indicate Type of Lease STATE X	FEE
	6. State Oil & Gas Lease No. B-1533 1/2	

P.O. Box 2088		300250472000			
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease STATE X FEE		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No. B-1533 1/2		
SUNDRY NOTICES AND REPORTS ON WELLS					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name		
1. Type of Well: OIL GAS WELL X WELL	OTHER		State C-20		
2. Name of Operator			8. Well No.		
Conoco Inc.			3		
3. Address of Operator			9. Pool name or Wildcat		
10 Desta Drive West, 1	Midland, TX 79705 (9	15) 686-6548	Eumont (011) Y-5R-QN		
4. Well Location					
Unit Letter F :1980	Feet From The north	Line and198	10 Feet From The west Line		
Section 20	Township 21S R	ange 36E I	NMPM Lea County		
<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	<i>\(\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>		
	GR 3620'				
11. Check A	ppropriate Box to Indicate	Nature of Notice Re	Prort or Other Data		
•		•	•		
NOTICE OF INTE		•	SEQUENT REPORT OF:		
•		•	•		
NOTICE OF INTE	ENTION TO:	SUB	SEQUENT REPORT OF: ALTERING CASING		
NOTICE OF INTE	ENTION TO: PLUG AND ABANDON	SUB:	SEQUENT REPORT OF: ALTERING CASING OPNS. PLUG AND ABANDONMENT		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	ENTION TO: PLUG AND ABANDON	SUBS REMEDIAL WORK COMMENCE DRILLING	SEQUENT REPORT OF: ALTERING CASING OPNS. PLUG AND ABANDONMENT		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. It is proposed to temp 1. Clean out to 3800	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS Corarily state all pertinent details, and corarily abandon this with bit and casing	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: Ind give pertinent dates, included well by the followed.	SEQUENT REPORT OF: ALTERING CASING OPNS. PLUG AND ABANDONMENT MENT JOB Ling estimated date of starting any proposed		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. It is proposed to temp. 1. Clean out to 3800' 2. Set CIBP at 3790'. 3. Circulate 80 bbls	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS Corarily state all pertinent details, and corarily abandon this with bit and casing of packer fluid.	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, include well by the follocraper.	SEQUENT REPORT OF: ALTERING CASING OPNS. PLUG AND ABANDONMENT MENT JOB Ling estimated date of starting any proposed		

I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE SIGNATURE TITLE	Regulatory Coordinator	11 date	/28/90	
TYPE OR PRIND NAME Jerry W. Hoover		TELEPHONE NO.	(915)	<u>68</u> 6-
				6548

APPROVED BY-

-- TITLE --

CONDITIONS OF APPROVAL, IF ANY: