

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 04724
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B 1533 1/2
7. Lease Name or Unit Agreement Name	State C-20
8. Well No.	7
9. Pool name or Wildcat	Eumont Yates 7 Rvrs Qn (Pro Gas)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Conoco Inc.	
3. Address of Operator 10 Desta Dr. Ste 100W, Midland, Tx., 79705-4500	
4. Well Location Unit Letter K 1980 Feet From The South Line and 1980 Feet From The West Line Section 20 Township 21S Range 36E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER Stuck pump, change tubing <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)/SEE RULE 1103.

rec'd 5/98

3-9-98: Move in and rig up, bled well down, try to unseat pump, backed off rods, POOH w/partial rods, prep to pull tubing.
3-10-98: Bled down well, killed well, pulled tbg to fluid swabbed well, got out with rods & tbg, SION.
3-11-98: Well pumped down, killed well, continued to RIH w/tbg, hot oiled, scanned tubing, RIH w/notch collars, left above perfs. SION.
3-12-98: Attempted foam air circulation, POOH, SION.
3-13-98: Killed well RIH w/SN 116 jts 2 3/8" took stripper head off, put stripper head and BOP back on POOH w/tbg, closed well in SD.
3-16-98: RIH w/collars & bit -tagged fill, RU swivel w/foam unit, drilled out to 3750', displaced hole, POOH - RIH w/SN & tbg, swabbed on well to clean well, tubing @ 3653'.
3-17-98: Swabbed on well, RIH w/sandline tagged up w/depthmeter, RD swab, killed well, took BOP off, flanged well up, move off. Converted to plunger lift.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ann E. Ritchie TITLE Regulatory Agent DATE 5-29-98

TYPE OR PRINT NAME Ann E. Ritchie TELEPHONE NO. 915 684-6381

(this space for State Use)

APPROVED BY ORIGINAL SIGNED BY TITLE GOV. VIK DATE OCT 26 1998

CONDITIONS OF APPROVAL, IF ANY: