

OIL CONSERVATION DIVISION

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-025-04727

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Citation Oil & Gas Corp.

3. Address of Operator
8223 Willow Place South, Suite 250, Houston, Texas 77070-5623

4. Well Location
Unit Letter **I** : **1980** Feet From The **South** Line and **660** Feet From The **East** Line

Section **20** Township **21S** Range **36E** NMPM **Lea** County

10. Elevation (Show whether DF, RKB, RT, GR, etc)
3609' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER:

orig per 3673-3914

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER:

OAP & install artificial lift

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU; POOH with tbg & RIH with bit to 3702'. Set CIBP @3618' & loaded hole with 53 BW. Ran CNL/GR/CCL & insp log 3617' - surf; TOC @2390'. RD, RIH with AD-1 pkr & tst'd 5-1/2" csg 775' - 3618' to 500# - OK. Pkr hung up @710' (worked free - lost 5 slip segments). RIH with bit to 3618'. RIH w/BV pkr, isolated csg leak 743' - 775'. RIH with magnet, rec'd 2 pkr slip segments (3 IH). Tagged CIBP @3618'. Dug out 7-5/8" BH, ND 5-1/2" WHD & csg valve. Set RBP @743' & PT csg 743' - surf to 1000#. POOH, ND BOP & 5-1/2" csg stub. Sqz'd HIC 743' - 775' with 125 sx "C"; circ'd to surf. Tag'd TOC @665' & drld cmt to 760'; PT sqz to 500#. RIH, perf'd 3330' - 3547'. Spotted 2 sx "C" on CIBP @3618' & RD. Spotted 250 gals 15% NEFe HCl 3330' - 3547'; acidized with 1250 gals 15% NEFe HCl, dropped 46 1.3 SG ball sealers - ISIP 740#. RD. Set pkr @3275', loaded 5-1/2" x 3-1/2" annulus with 20 bbls 2% KCl - tst'd to 500#. Frac'd 3330' - 3547' with 55M gals 60-70 quality CO2 foam carrying 7500# 20/40 sand & 87500# 12/20 sand tag'd with IR-192. Flushed to 275' w/treated FW - ISIP 1020#; 15 min 795#. Spotted 230 gals 15% NEFe acid @3233'. POOH - 3-1/2" tbg had unscrewed. Screwed into tbg & POOH. RIH, perf'd 2997' - 3226'. Set pkr @2885' & frac'd 2997' - 3226' with 55M gals 60-70 foam carrying 7500# 20/40 sand & 87500# 12/20 sand tagged with SC-46. Flushed with foam & linear gel. ISIP 810#; 15 min 419#. Opened well. Set BVP blanking plug in SN @2880' & PT to 500#. Perf'd tbg sub @2878'. Tagged sand @3090' (185' fill) & CO to 3268' (top of pkr); CHC. Engaged Arrow Set 1X pkr & rel'd pkr @3275'. RIH with bit, tagged sand @3508' & CO to 3605'. Flowed well to pit & pmp'd 25 bbls 2% KCl down csg to kill well. RIH with prod tubing; SN @3432'; BPMA 3518'; pump & rods. Put well on production 2/10/01. As of 2/21/01, well producing 0 BO; 5 BW & 627 Mcf with TP of 150 & CP of 13.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Debra Harris

TITLE

Prod./Reg. Coordinator

DATE

2/27/2001

TYPE OR PRINT NAME

Debra Harris

TELEPHONE NO.

(281) 517-7194

(This space for State Use)

APPROVED BY

TITLE

DATE