

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DEEPEN OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-04742
1. Type of Well Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Chevron USA, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator 15 Smith Rd. Midland, Tx 79705		7. Lease Name or Unit Agreement Name Eunice Monument South Unit
4. Well Location Unit Letter A 660 feet from the North line and 660 feet from the East line Section 21 Township 21-S Range 36-E NMPM County Lea		8. Well No. 437
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Post name or Well on Eunice Monument Grayburg S.A.

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTEREST ONLY		SUBSEQUENT REPORT OF	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	MULTIPLE COMPLETION ☐	CASING TEST AND CEMENT JOB ☐	OTHER: ☐
OTHER: ☐			

12. Describe proposed work to be completed (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RIH Tag CIBP @ 3730' (Grayburg Queen) Mix & Pump 30sx plug fr/3730' to 3450' Tag @ 3418'
2. Displace hole w/ 11 F, 9.5 # Brine w/ 25# Gel p/BBL
3. Spot 25sx plug fr 2400' to 2400' (D. Salt)
4. Spot 30sx plug fr 1150' to 1200' (7 5/8" shoe, T-salt) Tag @ 1150'
5. Spot 40sx plug fr 250' to surf (10 3/4" shoe- surf) Tag @ surf
6. Install dry hole marker 8-9-02

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: [Signature] TITLE: MANAGER DATE: 8-2-02
Type or print name: GARY W. WINK Telephone No. 915-208756
(This space for State Use) WINK SEE - 8-2-02
APPROVED BY: GARY W. WINK DATE: 8-2-02
Condition of approval, if any: OC FIELD REPRESENTATIVE II/STAFF MANAGER

GWW