NEV 1EXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or its agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations

NOTICE OF INTENTION TO TEST CASING SHUT-OFF	notice by checking below:	EPION TO CHOOSE	
<u> </u>	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL		
NOTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO FULL OR OTHERWISE ALTER CASING		
NOTICE OF INTENTION TO REPAIR WELL	NOTICE OF INTENTION TO PLUG WELL		
NOTICE OF INTENTION TO DEEPEN WELL			
	ink Texas	8-13-36	
OIL CONSERVATION COMMISSION,	2	Date	
Santa Fe, New Mexico.			
Gentlemen: Following is a notice of intentiton to do contain and	•		
Following is a notice of intentition to do certain work as Atlantic Oil Producing Go.			
Company or Operator Lease	State L Well N	in C. of	SE/N
of Sec. 22 , T. 21 S , R. 36 R	., N. M. P. M., E t	måre	Field.
County.			
FULL DETAILS OF PRO	OPOSED PLAN OF WA	ายน	
FOLLOW INSTRUCTIONS IN THE PARTY			
TODDOW INSTRUCTIONS IN THE RULE	S AND REGULATIONS OF The	HE COMMUNICATION	
TODAGO MASTRECTIONS IN THE RULE	CS AND REGULATIONS OF T	HE COMMISSION	
TOLLOW INSTRUCTIONS IN THE RULE	S AND REGULATIONS OF T	HE COMMISSION	
TORROW INSTRUCTIONS IN THE RULE	S AND REGULATIONS OF T	HE COMMISSION	
	S AND REGULATIONS OF T	HE COMMISSION	
Set 12 1/2" surface cas	ing at 292' w/	HE COMMISSION	
Set 12 1/2" surface cas	ing at 292' w/	HE COMMISSION	
	ing at 292' w/	HE COMMISSION	
Set 12 1/2" surface cas	ing at 292' w/	200 sx cent.	
Set 12 1/2" surface cas	ing at 292' w/	200 sx cent.	
Set 12 1/2" surface cas	ing at 292' w/	200 sx cent.	
Set 12 1/2" surface cas	ing at 292' w/	200 sx cent.	
Set 12 1/2" surface cas	ing at 292' w/	HE COMMISSION	
Set 12 1/2" surface cas	ing at 292' w/	200 sx cent.	
Set 12 1/2" surface cas	ing at 292' w/	200 sx cent.	
Set 12 1/2" surface cas Will bail hole dry	ing at 292' w/ and test for wa	200 sx cent. ter shut-off.	
Set 12 1/2" surface cas Will bail hole dry	ing at 292' w/ and test for wa	200 sx cent.	
Set 12 1/2" surface cas Will bail hole dry	ing at 292' w/ and test for wa	200 sx cent. ter shut-off.	
Set 12 1/2" surface cas Will bail hole dry	ing at 292' w/ and test for wa Atlantic O1:	200 sx cent. ter shut-off.	
Set 12 1/2" surface cas Will bail hole dry	ing at 292' w/ and test for wa Atlantic Oi By Position Superine	200 sx cent. ter shut-off.	
Bet 12 1/2" surface cas Will bail hole dry pproved	ing at 292' w/ and test for wa Atlantic Oi: By Position Supering Send commun	200 sx cent. ter shut-off. Producing Go Company or Operator ications regarding well to	
Set 12 1/2" surface cas	ing at 292' w/ and test for wa Atlantic Ot: By Position Supering Send community Name S. T. E	200 sx cent. ter shut-off. Producing Go Company or Operator ications regarding well to	