

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		<b>WELL API NO.</b> 30-025-04756
<b>1. Type of Well:</b> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		<b>5. Indicate Type of Lease</b> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
<b>2. Name of Operator</b> Chevron USA, Inc.		<b>6. State Oil &amp; Gas Lease No.</b>
<b>3. Address of Operator</b> 15 Smith Rd. Midland, Tx 79705		<b>7. Lease Name or Unit Agreement Name:</b> Eunice Monument South Unit
<b>4. Well Location</b> Unit Letter <b>K</b> : 1980 feet from the <b>south</b> line and 1980 feet from the <b>west</b> line Section <b>22</b> Township <b>21-S</b> Range <b>36-E</b> NMPM County <b>Lea</b>		<b>8. Well No.</b> 451
<b>10. Elevation (Show whether DR, RKB, RT, GR, etc.)</b>		<b>9. Pool name or Wildcat</b> Grayburg-San Andres

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Tag 5 1/2 CIBP @ 3738
2. Circ Hole w/MLF, 9.5# Brine w/25# Gel P/BBL.
3. Spot 25sx plug fr/3738 WOC Tag @ 3475
4. Spot 25sx plug fr/2610-2366
5. Spot 35sx plug @ 1558 WOC Tag @ 1172
6. Circ hole w/46sx to surf 5 1/2 csg fr/351
7. Rig down equipment. Install dry hole marker 10-31-02

Approved as to Plugging of the Well Bore.  
Liability under bond is retained until  
Surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER/SUNSET DATE 10-31-02

Type or print name Jimmy BAGLEY  
(This space for State use)

Telephone No 915 520-8756

APPROVED BY

Conditions of approval, if any:

CHIEF ENGINEER

CHIEF FIELD REPRESENTATIVE

DATE DEC 13 2002

GWW