

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL AP NO.
30-025-04758

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement

Eunice Monument South Unit

8. Well No.
433

9. Pool name or Wildcat
Eunice Monument Grayburg S.A.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Chevron USA, Inc.

3. Address of Operator
15 Smith Rd. Midland, Tx 79705

4. Well Location

Unit Letter A 660 feet from the North line and 660 feet from the East line

Section 22 Township 21-S Range 36-E NMPM County Lea

10. Formation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. RIH Tag CIBP @ 3688' (Grayburg Queen) spot 25sx plug fr/3688' to 3450' Tag @ 3408'

2. Displace hole w/MLF. 9.5# Brine w/25# Gel p/BBL

3. Spot 25sx plug fr/2600' to 2400' (B-salt)

4. Perf 4 holes @ 1500' sqz w/75sx fr/1500' to 1200' (7 5/8" shoe, T-salt) Tag @ 1158'

5. Perf 4 holes @ 250' circ cmt between 5 1/2' X 7 5/8" csg (13 3/8" shoe surf) w/80sx Tag cmt @ surf

6. Install dry hole marker 8-12-02

Approved as to Plugging of the Well Bore.
Liability under bond is retained until
Surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

[Signature] TITLE MANAGER DATE 12-02

Type or print name Jimmy Babin / SUPER
(This space for State use)

Telephone No. 915-205-756

APPROVED BY

Conditions of approval, if any:

ORIGINAL FILED IN

CARTER WINK

OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE DEC 13 2002

GWW

1

2