

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-04773
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name W. A. RAMSAY (NCT-B)
8. Well No. 2
9. Pool name or Wildcat EUMONT; YATES-7 RVRS-QUEEN (PRO GAS)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Chevron U.S.A. Inc.
3. Address of Operator P.O. Box 1150, Midland, TX 79702
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>25</u> Township <u>21S</u> Range <u>36E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CHEVRON PROPOSES TO:
PERF SQZ HOLES @ 2625'. ESTAB INJ RATE @ 2575' AND PMP 20 SX CMT. WOC.
TAG TOP OF CMT. PERF SQZ HOLES @ 350'. ESTAB INJ RATE 250' - SURF. PMP
CMT UNTIL WE HAVE GOOD RETURNS @ SURFACE (APPROX 80 SX CMT). PLACE CMT PLUG
250' - SURF. MONITOR CMT TOP. CUT OFF WH, SET DRY HOLE MARKER, CLEAN LOCATION.

TOS 1340

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. K. Ripley

TITLE TECHNICAL ASSISTANT

DATE 6/26/97

TYPE OR PRINT NAME J. K. RIPLEY

TELEPHONE NO. (915)687-7148

(This space for State Use)

ORIGINAL SIGNED BY DAVID WILLIAMS
DISTRICT SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JL

dp