

COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-935</b>	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>EXXON CORPORATION</b>		8. Farm or Lease Name <b>NEW MEXICO "G" STATE</b>
3. Address of Operator <b>P.O. BOX 1600, MIDLAND, TEXAS 79701</b>		9. Well No. <b>7</b>
4. Location of Well UNIT LETTER <b>N</b> <b>660</b> FEET FROM THE <b>SOUTH</b> LINE AND <b>1980</b> FEET FROM THE <b>WEST</b> LINE, SECTION <b>26</b> TOWNSHIP <b>21-S</b> RANGE <b>36-E</b> NMPM.		10. Field and Pool, or Wildcat <b>EUMONT YATES SEVEN RIVERS</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3546 GR</b>		12. County <b>LEA</b>



## 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-8-76, MIRU CSG PULLED S, PULLED RODS + TBG OUT OF HOLE, RN TBG IN HOLE TO 3848 SPOT 30 SK CMT PLUG, W.O.C. TAGGED PLUG AT 3575' LD HOLE W/BR MUD, SPOT 20 SK CMT PLUG AT 2800' W.O.C. TAGGED PLUG AT 2615' LAY DN 2 3/8" TBG, REMOVE WELLHD, WELD ONTO 5 1/2" CSG, WORKED CSG, SHOT @ 1207' WORKED FREE, LAY DN 5 1/2" CSG, RN TBG IN HOLE TO 1400', SPOT 50 SK CMT PLUG, W.O.C. TAGGED PLUG AT 1132', SPOT 35 SK CMT PLUG AT 375' W.O.C. TAGGED PLUG AT 250', LAY DN TBG, SPOT 10 SK PLUG AT SURFACE. INSTALL DRY HOLE MARKER. FRW 7-8-76

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE <b>UNIT HEAD</b>	DATE <b>7-30-76</b>
APPROVED BY 		DATE <b>AUG 10 1976</b>
CONDITIONS OF APPROVAL, IF ANY:		