

COPIES RECEIVED		
DISTRIBUTION		
SALE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-935	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator EXXON CORPORATION		8. Farm or Lease Name NEW MEXICO "G" STATE
3. Address of Operator P.O. BOX 1600, MIDLAND, TEXAS 79701		9. Well No. 14
4. Location of Well UNIT LETTER F 1980 FEET FROM THE NORTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 26 TOWNSHIP 21-S RANGE 36-E NMPM.		10. Field and Pool, or Wildcat EUMONT YATES SEVEN RIVERS
15. Elevation (Show whether DF, RT, GR, etc.) 3549 DF		12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-16-76, MIRU CSG. PULLERS, PULL RODS AND TBG FROM 3075'
SPOT 20 SX CNT PLUG, WAIT ON PLUG, TAGGED PLUG @
3660', LD HOLE W/MLD LADEN BRINE, SPOT 15 SX CNT PLUG
@ 2800', W.O.C., TAGGED CNT PLUG @ 2600', SPOT 15 SX
CNT PLUG @ 1500', W.O.C., TAGGED PLUG @ 1345', SPOT
15 SX PLUG @ 350', W.O.C., TAGGED PLUG @ 206', SPOT
10 SX CNT PLUG @ SURFACE, REMOVE WELL HEAD, INSTALL
DRY HOLE MARKER. F.R.W. 6-16-76

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE SECTION HEAD DATE 7-1-76

APPROVED BY [Signature] TITLE DATE 7-1-76
CONDITIONS OF APPROVAL, IF ANY: