

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION

Form O-103
Revised 1-1-89

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I

P.O. Box 1960, Hobbs, NM 88240

DISTRICT II

P.O. Drawer 60, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORM O-101 FOR SUCH PROPOSALS.		4. NO. assigned by OCD on New Well
5. Indicate Type of Lease STATE ☒ FEE ☐		6. State Oil & Gas Lease No. B-1732
7. Lease Name or Unit Agreement Name W.A. RAMSAY (NCT-A)		
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐		8. Well No. 2
2. Name of Operator CHEVRON U.S.A. INC.		9. Post name of Wellhead EUMONT
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE		
4. Well Location Unit Letter Section <u>M</u> <u>27</u> Township <u>21S</u> Range <u>36E</u> <u>660</u> Feet From The <u>WEST</u> Line County <u>LEA</u>		10. Elevation (show whether OF, F&B, R, or CR, etc.) 3586' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTER CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPER. ☐
OTHER: ☐	CASING TEST AND CMT. JOB ☐
	PLUG AND ABAND. ☒
	OTHER: ☐

12. Describe Proposed or Completed Operations Clearly, state all pertinent details, and give pertinent dates, including indicated date of starting any proposed work. SEE RULE 1103.

~~W.A. RAMSAY~~ **PLUG AND ABANDON WELL** *with surface* *0002 Aug 11 1992*
TIH WITH CIBP AND SET AT 3725' LOAD HOLE WITH FLUID AND TEST CASING.
SPOT 10 SX CMT ON TOP OF CIBP (3725-3620') COVER QUEEN PAY.
SET 25 SX BALANCED PLUG FROM 3135-3385, COVERS YATES & 7-RIVERS.
PERF AT 1715', UNABLE TO CIRC. CALLED OCD REP J. SEXTON, SPOT 15 SX PLUG
1771-1636', PERF @ 1610', WOULD NOT CIRC @ 1000#, SPOT 35 SX PLUG 1620-1360'.
SPOT 10 SX PLUG 100' TO SURFACE, CUT OFF WELL HEAD & ANCHORS
INSTALL P & A MARKER.
10# P & A MUD PLACED BETWEEN ALL CMT. PLUGS.
CHANGE WELL STATUS TO P & A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nita Rice TITLE TECHNICAL ASSISTANT DATE 10/26/92

TYPE OR PRINT NAME NITA RICE TELEPHONE NO. (915)687-7436

APPROVED BY [Signature] DATE FEB 05 1993

CONDITIONS OF APPROVAL (IF ANY):