

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department  
**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) <b>30-025-04805</b>	
6. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. <b>B-1732</b>	
7. Lease Name or Unit Agreement Name <b>W. A. Ramsay (NCT-A)</b>	
8. Well No. <b>46</b>	
9. Pool name or Wildcat <b>EUMONT GAS</b>	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) <b>3564' GL</b>	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator <b>CHEVRON U.S.A. INC.</b>	
3. Address of Operator <b>P.O. BOX 1150 MIDLAND, TX 79702</b>	
4. Well Location Unit Letter <b>E</b> : <b>1980</b> Feet From The <b>North</b> Line and <b>660</b> Feet From The <b>West</b> Line Section <b>27</b> Township <b>21S</b> Range <b>36E</b> NMPM <b>LEA</b> County	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) <b>3564' GL</b>	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
OTHER: <b>ADD PERFS</b> <input checked="" type="checkbox"/>	OTHER: <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including  
estimated date of starting any proposed work) SEE RULE 1103.

POH w/pkr & tbg. Clean out to 3680'. Set RBP @ 3190'; log.  
Perf 3128'-3586' w/4 JSPF. Test CIBP @ 3700' to 1000 psi. Acidize 3128'-3644'  
w/15% NEFE HCL. Frac 3584'-3644' w/CO2 gel & 12/20 sand. Flow or swab; tag sand fill,  
clean out. Frac 3129'-3490' w/CO2 gel & 12/20 sand. Flow or swab; tag sand fill,  
clean out.  
RIH w/prod tbg w/SN; set @ 3120'; return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>J. K. Ripley</u>	TITLE <u>T.A.</u>	DATE: <u>2/17/95</u>
TYPE OR PRINT NAME <u>J. K. Ripley</u>	TELEPHONE NO. <u>(915)687-7148</u>	
APPROVED BY <u>Paul Kautz</u> Geologist	TITLE <u>Geologist</u>	DATE <u>FEB 21 1995</u>
CONDITIONS OF APPROVAL, IF ANY:		