

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

JRM APPROVED  
Budget Bureau No 1004-0135  
Expires March 31, 1993

5 Lease Designation and Serial No.

NM 90162

6 If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT -" for such proposals

SUBMIT IN TRIPLICATE

1 Type of Well

☒ Oil Well ☐ Gas Well ☐ INJECTION Other

2 Name of Operator

CONOCO, INC.

3 Address and Telephone No.

10 Desta Dr., Suite 100W, Midland, Texas 79705-4500, 915 686-5424 915 684-6381

4 Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface: 660' FNL & 660' FEL  
TD: same as above

8 Name of lease & well

Lockhart B-28

Well #6

9 API Well #

30 025 04814

10 Field and Pool, or Exploratory Area

Eumont Yates 7 Rvrs Queen

11 County or Parish, State

Lea, NM

12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Pulled rods & tubing  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

10-19-98: Move in rig up, POOH w rods, RIH w/fishing tool, caught fish, jarred on pump, tool came loose, POOH laying down rods, kill well, ND wellhead, NU BOP, tagged for fill, POOH to rods & pump, wouldn't come free, SION.

10-20-98: Open up well, backed off rods, POOH - lay down rods, swab well down, pump stuck, rig up tuboscope, POOH - I good jt - rest bad, SION.

10-21-98: Rack & tally tbq, open up well, RIH w/ SN & tubing, NU wellhead, ND BOP, 2 3/8" tubing @ 3854', SN @ 3886', RU to run rods, pump chemical & flush down backside. SION.

10-23-98: Dumped 10 gals chemical & 10 bbls flush, RIH w/pump & rods. check pump action.

14 Thereby certify that the foregoing is true and correct.

Signed

Title

Ann E. Ritchie  
REGULATORY AGENT

Date 2-16-99

(This space for Federal or State office use)

ORIGINAL SIGNED BY CHRIS WILLIAMS

Approved by

DISTRICT 1 SUPERVISOR

Title

Date

Conditions of approval, if any