

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1991
1. Lease Designation and Serial No.
NM 90180
2. Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil ☐ Gas ☐ Other
☒ Well ☐ Well ☐ Other

2. Name of Operator

CONOCO INC

3. Address and Telephone No.

10 Depts Drive STE 100W, Midland, TX 79705 (915) 832-2551

4. Location of Well (Foolage, Sec., T., R., M., or Survey Description)

SEC. 28, T-213, R-36E, LTR 'A'

7. Unit or CA, Agreement Designation

5. Well Name and No.

LOCKHART R-28 # 6

9. API Well No.

90-025-04814

10. Field and Pool, or Exploratory Area

BUMONT VATES 7 EVERS QUE

11. County or Parish, State

LEA NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other

ADDITIONAL PAY

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log forms.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

10-31-94 MIRU. POOH W/RODS & PUMP. POOH W/PROD STRING. RIH W/ BIT & SCRAPER TO 3916. RIH W/RBP @ 2881' & PKR @ 2871'. TEST HELD. RESET RBP @ 3731 & PKR @ 3751. WOULD NOT TEST. RESET RBP @ 3360' & PKR WOULD NOT SET. COULD NOT RET. RBP. POOH W/PKR. RIH W/O. CAUGHT & RET RBP. RIH W/RBP & PKR. SET RBP @ 3360 & PKR @ 3350. TEST GOOD. REL TOOLS. RIH SET RBP @ 3750 & PKR 3750. TAG SAND @ 3691. POOH. SET PKR @ 3374. FRAC: PUMP 620 BBL 60 QUALITY. CO2 FOAM PAD. 387 BBL 60 TO 50 QUALITY CO2 FOAM. RAMPING 262.000# 12/20 BRADY 1 TO 8#. REL ON/OFF TOOL. POOH. RIH W/RBP @ 3348. PKR @ 2978. SPEARHEAD 75 BBL 15% HCL W/METHANOL. PUMP 739 BBL 60 QUALITY CO2 FOAM-RAMPING 148.000# 12/20 BRADY SAND 1 TO 8#. REL PKR. POOH. RIH W/NC ON PROD TBG. TAG SAND @ 3300. CO TO 3340. RIH TO RBP @ 3348. LATCH ON & POOH. RIH & TAG SAND @ 3354. CO TO PKR @ 3374. POOH W/PKR. RIH W/TEST PKR @ SET @ 3360. POOH W/PKR. RIH W/NC. SN. PROD TBG. TAG SAND @ 3747. POOH W/TBG. RIH W/RETRIEVING HEAD. POOH W/RBP. RIH W/PROD TBG. RIH W/RODS & EXCHANGE PUMP. LOAD TBG. GOOD PUMP ACTION. RDNO 11-11-94

14. I hereby certify that the foregoing is true and correct.

Signed

Title

STAFF REGULATORY ASSISTANT

Date

1-10-95

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: