

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. OIL & GAS COMMISSION
P.O. BOX 1980
HOBBS, NEW MEXICO 88240

FORM APPROVED
Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
CONOCO INC.

3. Address and Telephone No.
10 Desta Drive STE 100W, Midland, TX 79705 (915) 686-6551

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650' FNL, 2310' FWL
SEC. 30, T-21S, R-36E, UNIT LTR 'F'

5. Lease Designation and Serial No.

NM 62664

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

LOCKHART A-30 # 6

9. API Well No.

30-025-04837

10. Field and Pool, or Exploratory Area

EUMONT VATES 7-RVRS ON (PR)
11. County or Parish, State

LEA, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other ADDITIONAL PAY
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

10-19-94 MIRU. RIH W/2 3/8 PROD TBG & RET HEAD TO RBP @ 3275'. POOH W/RBP. RIH W/OS-2 3/8 GRAPPLE TO 3689'. POOH TOOLS PACKED W/FES04. RIH W/BIT & SCRAPER TO 3689'. POOH. RIH W/OS & 3 1/16 GRAPPLE-WENT OVER FISH. POOH. RIH W/OS & 2 3/8 GRAPPLE. CAUGHT FISH. POOH W/TBG & SN. RIH W/BIT & SCRAPER TO 3775'. POOH. PERF W/2 JSPF 3439-42-46-48-50-58-61-63-65-72-3512-15-18-20-23-42-46-55-79-81-83-86-3600-02-04-09-14-55-57-60-62-71-73-80-82-91. RIH W/TBG PKR ON 2 3/8 TBG. SET PKR @ 3258'. BREAKDOWN EUMONT PERES W/5000GAL 15% HCL W/METHANOL-DIVERTING W/1.3 BALL SEALERS. AIR-5.7BPM. AIP-2300#. 1SIP-0#. RELEASE PKR. RIH TO KNOCK BALLS OFF PERES. POOH. FRAC EUMONT W/1121 BBL PAD. FOLLOWED W/2449 BBL CO2 FOAM-RAMPING 12/20 BRADY 1/2# TO 8#. BLUSH W/57BBL FOAM. SAND TAGGED W/IRIDIUM. 1SIP-1570 5MIN, 10MIN, 15MIN-1485. AIR-70BPM AIP-2100#. RIH W/NC.SN.2/3 8 TBG. TAG SAND @ 3575. LAND TBG W/SN @ 3531'. RIGGED DOWN. 10-31-94

13 1994

SJS

HOBBS, NEW MEXICO

14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Title STAFF REGULATORY ASSISTANT

Date 11-5-94

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

Date _____

RECEIVED

DEC 15 1994

OCD HOBBS
OFFICE