

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.
-

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER-
2. Name of Operator
TEXACO Inc.
3. Address of Operator
P.O. Box 728, Hobbs, New Mexico
4. Location of Well
UNIT LETTER **J** **2310** FEET FROM THE **South** LINE AND **1650** FEET FROM
THE **East** LINE, SECTION **30** TOWNSHIP **21-S** RANGE **36-E** N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.)
3625' (DF)

7. Unit Agreement Name
-
8. Farm or Lease Name
J.K. Rector
9. Well No.
3
10. Field and Pool, or Wildcat
Eumont Yates Seven Rivers Queen
12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER Sqz perfs 3500'-3680' & reperforate	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Install BOP. Pull tubing & pkr.
2. Clean out to 3500'.
3. Set cement retainer @ 3464'. Squeeze 7" OD csg perforations 3500'-3680' w/100 sx Class C cement. Job compl. 2:15 p.m. 3-7-77.
4. Perforate 7" OD csg w/1 JSPF @ 3272, 78, 83, 90, 95, 3303, 10, 20, 26, 37, 45, 52, 61, 66, 72, & 3412'.
5. Set pkr @ 3133'. Acidize 7" OD casing perforations 3272'-3412' w/2500 gal. 15% HCl acid containing FE sequestant additive & 600# rock salt in 4 equal stages. Flush w/13 bbls KCl water.
6. Install pumping equipment. Complete as oil well in Eumont Yates Seven Rivers Queen.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Jerry Sexton* TITLE Asst. Dist. Supt. DATE 4-28-77
ORIG. SIGNED BY
Jerry Sexton
DIST. 1, Supt.
COPIES OF APPROVAL, IF ANY:

RECEIVED

MAY 3 1977

CL. COMMUNICATIONS COMM.
13554, L. B.