Form C-103 Revisied 1-1-89

Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

District Office		TVATION DIVISION		
P.O. Box 2088				
DISTRICT I	Santa Fe,	, New Mexico 87504-2088		
P.O. Box 1980, Hobbs, NM 88240			ARINO (OCD on New Wells
DISTRICT II			API NO. (sessigned by OCD on New Wells) 30-025-04876	
P.O. Drawer Dd, Artesia, NM 88210			5. Indicate Type of	
DISTRICT III 1000 Rio Brazos Rd., Aztec, Nm 87410			5. Holicate Type 0	STATE X FEE
			6. State Oil & Ga B-229	e Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			200	Manteria de la companya de la constituencia de la constituencia de la constituencia de la constituencia de la c
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name J. F. JANDA (NCT-B)	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"				
(FORM C-101) FOR SUCH PROPOSALS.)				
1. Type of Well:			7	
OIL	GAS			
WELL	WELL X OTHER			
2. Name of Operator			8. Well No.	
CHEVRON U.S.A. INC.			9. Pool name or Wildcat	
9. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: WENDI KINGSTON			SOUTH EUN	
A Well conting				
Unit Letter	O : 660 Feet Fr			Feet From The EAST Line NMPM LEA County
Section 32	Towns	hip 215 Range Devetion(Show whether DF, RKB, RT, GR, etc.)	36E	NMPM LEA County
	10. 2	3614' GL		inder the second of the second
11 Check Appropriate Box to Indecate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
	PLUG AND ABANDON	REMEDIAL WORK	7	ALTER CASING
PERFORM REMEDIAL WORK		COMMENCE DRILLING OPNS.	=	PLUG AND ABAN.
TEMPORARILY ABANDON	CHANGE PLANS	CASING TEST AND CMT JOB	-	
PULL OR ALTER CASING				
отнея:		OTHER:		
12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including				
12. Describe Proposed or Completed Operations(Clearly state as partition), describe restricted date of starting any proposed work) SEE RULE 1103.				
WORK STARTED 01/04/95:				
PLUG #1, SET CIBP AT 3350' AND SET 25 SX CMT ON TOP, TOC @3110'.				
PLUG #2, 20 SX PLUG FROM 1390'-1630', COVERS SALT ZONE.				
PLUG #3, PERF & SQZ 40 SX PLUG FROM 380'-480', COVERING 8 5/8" SHOE.				
PLUG #4, PERF & SQZ 45 SX PLUG FROM 50'-SURFACE.				
ALL PLUGS ARE CLASS C NEAT MIXED AT 14.8 PPG, 1.32 CU/FT SX. DISPLACE				
HOLE W/9.5 PPG MUD LADEN FLUID. PULL DEAD MAN ANCHORS, FILL PITS, LEVEL LOCATION,				
PLACE P&A MARKER & CHANGE STATUS OF WELL TO P&A 01/09/95.				
I hereby certify that the information	above is true and complete to the best of my	y knowledge and belief.	DATE	1 12 4 10 5
SIGNITURE	TITLE	TECH. ASSISTANT	DATE:	1/24/95
TYPE OR PRINT NAME	WENDI KINGSTON		TELEPHONE NO.	(915)687-7826
ORIGI	NAL SIGNED BY		DATE	MAR 13 1995
	ARY WINK			
F	ELD REP. II			



Of s