Submit 3 Copies to Appropriate

District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

ALTER CASING

PLUG AND ABAN.

District Office

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER:

District Office	OIL	CONSERVA	HON DIVI	SION					
		P.O. Bo	x 2088						
DISTRICT I		Santa Fe, Nev	v Mexico 87	504-2088					
P.O. Box 1980, Hobbs, NM 88240				00.2000					
DISTRICT II					ARLNO (				
P.O. Drawer Dd, Artesia, NM 88210						signed by OCD on Ne	w Wells)		
DISTRICT III 1000 Rio Brazos Rd., Aztec, Nm 87410						30-025-04902			
						5. Indicate Type of Lease			
					<u> </u>	STATE	<u> </u>	EE	
					6. State O	il & Gas Lease No.		· · · · · · · · · · · · · · · · · · ·	
					N/A				
SU	NDRY NOTICE	S AND REPORTS	ON WELLS						
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						ma ar Unio A			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"						7. Lesse Name or Unit Agreement Name W.A. RAMSAY (NCT-A)			
	(FORM C-101) FO	R SUCH PROPOSALS	5.)		1	(11C)-7	~!		
1. Type of Well:		······································		<del></del>	Ⅎ				
OIL	GAS				1				
WELL	WELL X	OTHER							
2. Name of Operator		·			B. Well No.		··		
CHEVRON U.S.A	. INC.				D. Well No.	20			
3. Address of Operator		<del></del>			<del> </del>	38			
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS						9. Pool name or Wildcat SOUTH EUNICE~ Sアーのよ			
4. Well Location					12001H	FOINICE - 2X	44		
Unit Letter	:	1980 Feet From The	SOUTH	Line and		660 Feet From Th	\A/EC	-	
Section 34		Township	21\$	Range	36E				
		10. Elevation(S	show whether DF, RK	B, RT, GR, etc.)	JUL	NMPM	LEA	County	
			3573 GE						
11	Check Appropriate I	Box to Indecate Natu		ort, or Other Date					
NOTICE OF INTE	NTION TO:	1		BSEQUENT RE	DODT OF				
			30	DOCKOCIAL ME	FUKI UF:				

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CMT JOB

**COMPLETE IN SOUTH EUNICE** 

 Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including esticated date of starting any proposed work) SEE RULE 1103.

PLUG AND ABANDON

CHANGE PLANS

MIRU, POOH WITH PRODUCTION EQUIP.

SET CICR AT 3750', SQUEEZE OFF PERFS AT 3771-3885 WITH 100 SXS. CMT. OBTAINED 1500#.

OTHER:

PERFORATED WITH 4" GUNS, 180 DEG. PHSD, 2 JHPF, 3568-3708, 62 HOLES.

ACIDIZED WITH 5500 GALS. OF 20% NEFE HCL.

REPERFORATED 3568-72 AND 3638-44, SPOT ACID ACROSS NEW PERFS.

FRAC PERFS 3568-3708 WTIH 30# GUAR GEL AND 43,000# OF 16/30 BRADY SAND.

TIH WITH COIL TBG. AND CLEAN OUT TO PBTD AT 3740'.

FLOW WELL BACK.

INSTALL PRODUCTION TUBING AND RODS.

WORK STARTED 6-28-92, ENDED 7-9-92.

I hereby certify that the inform	etion above is true and complete to the	best of my kno	owledge and belief.		
SIGNITURE 7.	2. matthews	TITLE	TECH. ASSISTANT	DATE:	7-17-92
TYPE OR PRINT NAME	P.R. MATTHEWS			TELEPHONE NO.	(915)687-7812
APPROVED BY	Orig. Signed by Paul Kautz FANY: Geologist	TITLE		DATE	JUL 20 '92