

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-04911

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
Chevron U.S.A. Inc.

3. Address of Operator
P.O. Box 1150, Midland, TX 79702

4. Well Location
Unit Letter M : 330 Feet From The SOUTH Line and 330 Feet From The WEST Line
Section 34 Township 21S Range 36E NMPM LEA County

7. Lease Name or Unit Agreement Name
W. A. RAMSAY (NCT-A) COM

8. Well No.
1

9. Pool name or Wildcat
JALMAT; TAN-YATES-7 RVRS (PRO GAS)

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3562'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CHEVRON PROPOSES TO:
POH W/TBG. SET CICR @ 3055'. PMP 243 SX CL "C" CMT. PLACE 49 SX CL "C" ON CICR @ 3055'.
RUN CBL & FREE POINT LOCATOR 2850'-2150'. ATTEMPT TO BACK OFF CSG BETWEEN 2850' & 2300'. POH
W/8-1/4" CSG. SPOT 100 SX CL "C" 50' ABOVE & BELOW TOP OF 8-1/4" CSG. SET CICR @ 2180'. PMP
70 SX CL "C". PLACE 20 SX CL "C" ON CICR @ 2180'. SET BALANCED PLUG 1685'-1405' W/130 SX
CMT. PERF 8 SQZ HOLES @ 930' W/4 JHPF. SET CICR @ 880'. CIRC 120 SX CL "C" THRU 15" &
12-1/2" ANN. CIRC 69 SX CL "C" THRU 12-1/2" & 10" ANN. PLACE 20 SX CL "C" ON CICR @ 880'.
PERF 8 SQZ HOLES @ 320' W/4 JHPF. SET CICR @ 270'. CIRC TO SURF W/300 SX CL "C" IN 20" & 15"
ANN. CIRC TO SURF W/175 SX CL "C" IN 15" & 12-1/2" ANN. CIRC TO SURF W/120 SX CL "C" IN
12-1/2" & 10" ANN. PLACE 20 SX CL "C" ON CICR @ 270'. SET BALANCED PLUG 100' - SURF W/25 SX
CL "C". CUT OFF WH, WELD ON DRY HOLE MARKER, CMT. CUT OFF ANCHORS, CHANGE WELL STATUS TO
P&A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE TECHNICAL ASSISTANT DATE 4/18/97

TYPE OR PRINT NAME J. K. RIPLEY TELEPHONE NO. (915)687-7148

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JC dp

