Submit 3 Copies to Appropriate

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office	OIL CON	ISERVATIO	N DIVISION	i i			, , ,		
		P.O. Box 208	8						
DISTRICT I	Sant	a Fe, New Me	xico 87504-:	2088					
P.O. Box 1980, Hobbs, NM 88240									
DISTRICT II					API NO. (assigne	ed by OCD on New V	Velis)	_	
P.O. Drawer Dd, Artesia, NM 8821	0				30-025-04	912			
DISTRICT III 1000 Rio Brazos Rd., Aztec, Nm 8	7410				5. Indicate Typ		X FEE	_	
					ļ				
					8. State Oil & Gas Lease No.				
	·				002708				
SUNDRY NOTICES AND REPORTS ON WELLS									
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					7. Lease Name	or Unit Agreement N	iame		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					W. A. RAM	ISAY (NCT-A))		
	(FORM C-101) FOR SUCH	PROPOSALS.)							
Type of Well: OIL	GAS				ŀ				
WELL	WELL X OTHER								
2. Name of Operator					8. Well No.	" · · · · · · · · · · · · · · · · · · ·		_	
CHEVRON U.S.A. INC.					13				
3. Address of Operator					9. Pool name or	r Wildcat		_	
	ND, TX 79702 ATTN: WE	ENDI KINGSTON	<u> </u>		EUMONT;Y	ATES-7 RVR	S-QUEEN(PRO (GΑ	
4. Well Location	B : 660		NORTH		100				
Unit Letter Section 35		Feet From The 21S	NORTH	Line and		O Feet From The	EAST Line	0	
Section		Township 21S 10. Elevation(Show wi	hether DE RYR BT /	Range	36E	NMPM	LEA cou	unty	
			3548'	Grt, 6(c.)					
11	Check Appropriate Box to I	ndecate Nature of N	otice, Report, or (Other Data				ш	
NOTICE OF	INTENTION TO:		SUBSEC	LUENT RE	PORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMED	IAL WORK	X	1	ALTER CASING			
TEMPORARILY ABANDON	CHANGE PLANS	соммі	ENCE DRILLING OPNS	s.	1	PLUG AND ABAN	.		
PULL OR ALTER CASING	CASING	TEST AND CMT JO	8	1					
OTHER:		OTHER:	PLUGBAC	CK					
	ed Operations(Clearly state all pertinent	t details, and give pertin	ent dates, including			· · · · · · · · · · · · · · · · · · ·		_	
esticated date of starting any pr	oposed work) SEE NOLE 1103.								
MIDLLOO	131 IOE SET CIRD @3500	L DUN COMO D	000000774	TDOMES	0 = 10 + 0 = -				
NIITU UO	/31/95. SET CIBP @3500	. RUN CUMP P	OHOSIIY NEU	I KON LO	G F/3499'-1	500',			

MIRU 08/31/95. SET CIBP @3500'. RUN COMP POROSITY NEUTRON LOG F/3499'-1500', RUN CBL F/3499'-2700'. PERF F/3373'-2900'. ACDZ PERFS W/3300 GALS 16% ACID. FRAC PERFS W/51500 GALS 50Q CO2 GEL AND 227,000 LBS 12/20 SD. RIH W/2 3/8" TBG TO 3471', PKR @2814'.

WORK ON WELL COMPLETED ON 9/11/95.

	2			
I hereby certify that the SIGNITURE	information above to true and complete to the best of my know	ledge and belief. TECH. ASSISTANT	DATE:	09/26/95
TYPE OR PRINT NAME	WENDI KINGSTON		TELEPHONE NO.	(915)687-7826
APPROVED BY	ORIGINAL STONED BY JERRY SEXTON DISTRICT E SUPERVISOR TITLE		DATE	00T 2 0 1035
CONDITIONS OF APPRO	OVAL IF ANY:			