

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-04922
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1732
7. Lease Name or Unit Agreement Name	W. A. RAMSAY (NCT-A)
3. Well No.	3
9. Pool name or Wildcat	EUMONT; YATES-7 RVRS-QUEEN (OIL)
4. Well Location	Unit Letter 0 : 660 Feet From The SOUTH Line and 1980 Feet From The EAST Line
Section 35 Township 21S Range 36E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3568' GL

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
Chevron U.S.A. Inc.

3. Address of Operator  
P.O. Box 1150, Midland, TX 79702

4. Well Location  
Unit Letter 0 : 660 Feet From The SOUTH Line and 1980 Feet From The EAST Line  
Section 35 Township 21S Range 36E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3568' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OP'NS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH W/TBG. PUMP 150 SX CL "C" @ 3700', WOC; TOC @ 3120'.  
LOAD HOLE W/P&A MUD. SET 40 SACK CMT PLUG @ 1464'.  
PERF @ 84', ATTEMPTED TO PUMP DOWN 6" & 8-5/8" 700#; FOUND CMT IN 8-5/8" VALVE, CMT HAD  
ALREADY BEEN CIRC. PAUL (OCD) GAVE PERMISSION TO SET 100' SURF PLUG.  
SET 100' SURF PLUG.  
CUT OFF WELLHEAD & ANCHORS; INSTALL DRY HOLE MARKER.

WELL P&A'D 2/6/95

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE TECHNICAL ASSISTANT DATE 9/24/96  
TYPE OR PRINT NAME J. K. RIPLEY TELEPHONE NO. (915)687-7148

(This space for State Use)

APPROVED BY Charles Harris TITLE OIL & GAS DIVISION DATE JAN 22 1997  
CONDITIONS OF APPROVAL, IF ANY:

