

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-025-04933
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1732-1
7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT
8. Well No. 127
9. Pool name or Wildcat ARROWHEAD/GRAYBURG

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX. 79702 ATTN: P.R. MATTHEWS	
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>36</u> Township <u>21S</u> Range <u>36E</u> NMPM IEA County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3530 GE</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: <u>DEEPEN, ACDZ., LOG</u> ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU, POOH WITH PROD. EQUIP. SET RBP AT 3700 , TST/CSG. TO 500 PSI-OK. TIH WITH
4 3/4" BIT CO FILL TO 3808'. DRILL ON JUNK 3808-3816. SET PACKER AT 3573, PUMP 100 SXS.
CMT. DRILL OUT CMT. TO 3816, SET CIGR AT 3573, PUMP 75 SXS. CMT.
DRILL CMT. 3570-73, DRILL CIGR AT 3573. DRILL TO 3817. PUMP 25 SXS. CMT., DRILL
CMT. 3602-3759, DRILL 3759-3870. LOG HOLE: NEUTRON-DENSITY-GR-CAL-CCL-DLL.
ACDZ. OH 3731-3870 W/1000 GALS. 15% NEFE. SWB/TST. SQZ. ZONE 6 WITH 59 SXS. CMT.
DRILL CMT. 3544-3834. SWB/TST. ACDZ 3730-3834, W/1000 GALS. 15% NEFE. SWB/TST.
SELECTIVELY PERF 3652-3818 W/ 4" CSG. GUNS, 2 JHPF, 134 HOLES.
ACDZ. 3704-3652 W/ 1500 GALS. 15% NEFE. SWB/TST. CONTINUE ON BACK.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE P.R. Matthews TITLE TECHNICAL ASSISTANT DATE 9-3-91
TYPE OR PRINT NAME P.R. MATTHEWS TELEPHONE NO. 687-7812

(This space for State Use)

APPROVED BY ERRY LEXTON TITLE INSOR DATE
CONDITIONS OF APPROVAL, IF ANY:

TH WITH PRODUCTION EQUIPMENT. EOL AT 3814'
WORK STARTED 8-9-91, WORK ENDED 9-2-91.