

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)	
30-025-04934	
6. Indicate Type of Lease	
STATE <input checked="" type="checkbox"/>	FEE <input type="checkbox"/>
8. State Oil & Gas Lease No.	
N/A	
7. Lease Name or Unit Agreement Name	
HARRY LEONARD (NCT-C)	
8. Well No.	
7	
9. Pool name or Wildcat	
EUMONT Y/SR/QN	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
1. Type of Well:			
OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>	
2. Name of Operator			
CHEVRON U.S.A. INC.			
3. Address of Operator			
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS			
4. Well Location			
Unit Letter	G	1980 Feet From The	NORTH
Section	36	Township	21S
		Line and Range	1980 Feet From The EAST
		36E	NMPM LEA
		County	
10. Elevation(Show whether DF, RKB, RT, GR, etc.)			
3531 GE			

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CMT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: RECOMPLETE IN THE PENROSE <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU,POOH WITH PRODUCTION EQUIP.
CLEAN OUT TO TD AT 3640'.
SET CICR AT 3121'.
PUMP 200 SXS. OF CEMENT INTO QUEEN PAY AT 3307'.
DRILL OUT TO TD AT 3640'.
PERF AT 3452-3627,49 HOLES,1 JHPF.
ACDZ WITH 100 GALS OF 15% NEFE AND SWAB BACK.
FRAC PERFS WITH SAND AND CO2. FLOW WELL BACK.
CLEAN WELL OUT TO 3640'.
TRIP IN HOLE WITH PRODUCTION EQUIPMENT.
SET PACKER AT 3367'. RETURN TO PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE	<i>P.R. Matthews</i>	TITLE	TECH. ASSISTANT
		DATE:	1-21-92
TYPE OR PRINT NAME		P.R. MATTHEWS	
		TELEPHONE NO.	(915)687-7812
ORIGINAL SIGNED BY JERRY SEXTON			
APPROVED BY	DISTRICT I SUPERVISOR	TITLE	
CONDITIONS OF APPROVAL, IF ANY:		DATE	JAN 23 '92