

- No. 9 - 1 Hour Cook Drill Stem Test from 6897-6950' with 5/8" choke at 6877'. Packers at 6892-6897'. Bombs at 6945-6948'. Tool opened 2:15AM 11-18-56. Fair blow of air 15 minutes, dead 45 minutes. Recovered 10' drilling mud, no shows. HP 3300#. FP 40#. 15 minute BHP 80#.
- No. 10 1 Hour Cook Drill Stem Test from 8189-8235' with 5/8" choke at 8174'. Packers at 8189-8184'. Bombs at 8230-8233'. Tool opened 7:55PM 11-30-56. Very weak blow air surface 5 minutes and died. Recovered 15% Drilling mud, no shows. HP 4100#. FP 0#. 30 minute BHP 0#.
- No. 11 1 Hour Cook Drill Stem Test from 8275-8397' with 5/8" choke at 8259'. Packers at 8269-8275'. Bombs at 8390-8395'. Tool opened 8:40PM 12-2-56. Weak blow of air throughout test. Recovered 270' gas cut drilling mud, no shows. HP 4140#. FP 90-180#. 30 minute BHP 1940#.
- No. 12 1 Hour Cook Drill Stem Test from 8396-8435' with 5/8" choke at 8381'. Packers at 8391-8396'. Bombs at 8430-8433'. Tool opened 11:05PM 12-3-56. Weak blow air 15 minutes, died. Recovered 300' drilling mud, no shows. HP 3920#. FP 100-180#. 30 minute BHP 2340#.
- No. 13 2 Hour Cook Drill Stem Test from 8434-8526' with 5/8" choke at 8421'. Packers at 8429-8526'. Bombs at 8518-8523'. Tool opened 3:PM 12-5-56. Good blow of air, decreased at end of test. Recovered 7563' fluid, 163' sulphur wtr cut mud, 7400' salty sulphur water, no shows. HP 3930#. FP 460-3340#. 30 minute BHP 3420#.
- No. 14 1 Hour Cook Drill Stem Test from 9045-9093' with 5/8" choke at 9030'. Packers at 9040-9045'. Bombs at 9040-9091'. Tool opened 8:05AM 12-12-56. Bubble air 1 minute, died. Recovered 20' drilling mud, no shows. HP 4260#. FP 40#. 30 minute BHP 40#.
- No. 15 2 Hour Cook Drill Stem Test from 9496-9541' with 5/8" choke at 9500'. Packers at 9491-9496'. Bombs at 9536-9539'. Tool opened 11:10AM 12-18-56. Fair blow air throughout test. Recovered 4020' fluid, 240' gas cut drilling mud, and 3780' salt water, no shows. HP 4540#. FP 380-2100#. 30 minute BHP 2480#.
- No. 16 1 Hour Cook Drill Stem Test from 9805-9828' with 5/8" choke at 9787'. Packers at 9823-9828'. Sub 9502'. Tool opened 9:12PM 12-24-56. Weak blow air throughout test. Recovered 210' drilling mud, no shows. HP 4520#. FP 20-120#. 30 minute BHP 2860#.
- No. 17 1 Hour Cook Drill Stem Test from 9840-9880' with 5/8" choke at 9824'. Packers at 9834-9840'. Bombs at 9875-9878'. Tool opened with weak bubbles air and died. Recovered 390' slightly gas cut mud, no shows. HP 4540#. FP 40-160#. 30 Minute BHP 4040#.
- No. 18 2½ Hour Cook Drill Stem Test from 9880-9930' with 5/8" choke at 9862'. Packers at 9874-9880'. Bombs at 9925-9928'. Tool opened 1:18PM 12-27-56. Weak blow air throughout test. Recovered 1395' salt water, no shows. HP 4780#. FP 100-600#. 30 minute BHP 2160#.

- No. 1 - 1 hour Cook Drill Stem Test from 8897-8901 with 5/8" choke at 8897.  
Packers at 8892-8897. Bore at 8895-8897. Tool opened 8:15 AM 12-26.  
Fair flow of air 15 minutes, dead 45 minutes. Recovered 10' drilling mud,  
no shows. BP 3300%. 15 minute BHP 10%.
- No. 2 - 1 hour Cook Drill Stem Test from 8189-8221 with 5/8" choke at 8174.  
Packers at 8189-8194. Bore at 8230-8231. Tool opened 7:55 AM 12-30-26.  
Very weak flow air surface 5 minutes and died. Recovered 15' drilling  
mud, no shows. BP 4100%. 30 minute BHP 0%.
- No. 3 - 1 hour Cook Drill Stem Test from 8275-8347 with 5/8" choke at 8259.  
Packers at 8269-8275. Bore at 8380-8381. Tool opened 8:40 AM 12-2-26.  
Fair flow of air throughout test. Recovered 270' gas cut drilling mud,  
no shows. BP 4100%. 30 minute BHP 100%.
- No. 4 - 1 hour Cook Drill Stem Test from 8398-8431 with 5/8" choke at 8381.  
Packers at 8391-8396. Bore at 8430-8431. Tool opened 11:05 AM 12-3-26.  
Weak flow air 15 minutes, died. Recovered 300' drilling mud, no shows.  
BP 3200%. 30 minute BHP 2340%.
- No. 5 - 1 hour Cook Drill Stem Test from 8434-8526 with 5/8" choke at 8431.  
Packers at 8429-8526. Bore at 8518-8521. Tool opened 3:15 PM 12-5-26.  
Good flow of air, decreased at end of test. Recovered 753' fluid,  
light oil, salt water, no shows. BP 3200%.  
BP 46-3200%. 30 minute BHP 3420%.
- No. 6 - 1 hour Cook Drill Stem Test from 9045-9091 with 5/8" choke at 9030.  
Packers at 9040-9041. Bore at 9045-9091. Tool opened 8:05 AM 12-12-26.  
Fair air 1 minute, died. Recovered 20' drilling mud, no shows.  
BP 4200%. 30 minute BHP 14%.
- No. 7 - 1 hour Cook Drill Stem Test from 9490-9511 with 5/8" choke at 9500.  
Packers at 9491-9496. Bore at 9530-9531. Tool opened 11:05 AM 12-13-26.  
Fair flow air throughout test. Recovered 1020' fluid, 240' gas cut drilling  
mud, and 3760' salt water, no shows. BP 380-2100%. 30 minute  
BHP 2450%.
- No. 8 - 1 hour Cook Drill Stem Test from 9802-9828 with 5/8" choke at 9817.  
Packers at 9823-9828. Sub 9802. Tool opened 9:15 AM 12-24-26. Weak  
flow air throughout test. Recovered 210' drilling mud, no shows.  
BP 4200%. 30 minute BHP 2800%.
- No. 9 - 1 hour Cook Drill Stem Test from 9840-9880 with 5/8" choke at 9824.  
Packers at 9834-9840. Bore at 9875-9878. Tool opened with weak  
flow air and died. Recovered 390' slightly gas cut mud, no shows.  
BP 43-160%. 30 minute BHP 4040%.
- No. 10 - 1 hour Cook Drill Stem Test from 9880-9930 with 5/8" choke at 9881.  
Packers at 9874-9880. Bore at 9925-9928. Tool opened 1:15 PM 12-27-26.  
Fair flow air throughout test. Recovered 1335' salt water, no shows.  
BP 100-600%. 30 minute BHP 2160%.