

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name State "D" DE
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 2
4. Location of Well UNIT LETTER <u>J</u> <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or Wildcat Arrowhead Grayburg
15. Elevation (Show whether DF, RT, GR, etc.) 3515' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up on 8/3/76, killed well, installed BOP & POH w/completion assy. RIH w/5½" cmt retr on 2-3/8" OD EUE tbg, set retr @ 3665'. Pmpd 65 sx Cl C cmt cont'g 4% gel below retr. PO of retr & dumped 5 sx on top of retr 3665-3583'. Circ hole w/heavy gelled mud. POH w/tbg. Cut 5½" OD csg @ 2190', attempted to pull, could not pull. Cut 5½" OD csg @ 1976', rec 1976'. RIH w/2-3/8" tbg, spotted 45 sx Cl C cmt 2025-1793'. Spotted 55 sx Cl C cmt cont'g 4% gel 1235-1034' across 8-5/8" csg shoe & top of salt. Spotted 10 sx Cl C cmt @ surface. Installed regulation dry hole marker. P&A eff 8/9/76. Final Report.

Location cleaned & leveled. Your office to be notified when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Dist. Drlg. Supv.</u>	DATE <u>8/10/76</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>8/10/76</u>
CONDITIONS OF APPROVAL, IF ANY:		