

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2038
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-

3a. Indicate Type of Lease
State ☒ ☐ ☐
3. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Chevron U.S.A. Inc.

Address of Operator

P.O. Box 670, Hobbs, NM 88240

Location of Well

UNIT LETTER P 2970 FEET FROM THE South LINE AND 990 FEET FROM
THE East LINE, SECTION 2 TOWNSHIP 21S RANGE 37E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

Harry Leonard (NCT-F)

9. Well No.

#11

10. Field and Pool, or Wildcat
Wantz Abo

15. Elevation (Show whether DF, RT, GR, etc.)

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

REPAIR REMEDIAL WORK ☐
IMPROVEMENT ABANDON ☐
LL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

COMMENCE DRILLING OPERATIONS ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

abandon abo

Work performed: 12-30-87 through January 2, 1988

PB: 7075 TD: 7542

POOH w/ production equipment, tie into TOL at 5131, RIH w/ CIBP, set at 7110, RIH w/ bailer and cap CIBP w/35 ft cement, PBTD 7075'. (2 sx cmt), SIFN, RIH w/ 2 3/8" J-55 tbg to 7028.36', load hole w/ 200 bbl prod. wtr, tst csg 500psi, 30 min, ok. NU BOP, NU WH, RIH w/ pmp, rods, hang on clamp, RD MO PU. Turn over to Shell as unit operator, final report from drilling, Chevron.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

M. E. Seay

TITLE Staff Drilling Engineer

DATE January 8, 1988

Eddie W. Seay

Oil & Gas Inspector

TITLE

DATE

JAN 12 1988

ADDITIONS OF APPROVAL, IF ANY:

ZA wantz abo (held) 1-14-88

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATION	

OIL CONSERVATION DIVISION
P. O. BOX 2038
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-

1a. Indicate Type of Lease
State ☒ Fee ☐
3. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
Name of Operator Chevron U.S.A. Inc.	8. Farm or Lease Name Harry Leonard (NCT-F)
Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Well No. #11
Location of Well UNIT LETTER <u>P</u> <u>2970</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or WHOLE Wantz Abo
11. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

REFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
IMPROPERLY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
LL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to set a CIBP above the top perf in the Abo Formation. Work is an operating necessity as a working interest owner in the forthcoming Northeast DRinkard Unit. (Shell operated)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

by M. E. Ahn TITLE Staff Drilling Engineer DATE Dec. 7, 1987

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

DEC 9 1987