

NEW MEXICO OIL CONSERVATION COMMISSION  
WELL LOCATION AND ACREAGE DEDICATION PLAT

Form C-102  
Supersedes C-128  
Effective 1-1-65

All distances must be from the outer boundaries of the Section.


Operator <b>SHELL WESTERN E&amp;P INC.</b>			Lease <b>STATE SECTION 2</b>		Well No. <b>3</b>
Unit Letter <b>U</b>	Section <b>2</b>	Township <b>21S</b>	Range <b>37E</b>	County <b>LEA</b>	
Actual Footage Location of Well: <b>660</b> feet from the <b>SOUTH</b> line and <b>660</b> feet from the <b>WEST</b> line					
Ground Level Elev. <b>3467' DF</b>	Producing Formation <b>WANTZ ABO</b>		Pool <b>WANTZ ABO</b>		Dedicated Acreage: <b>40</b> Acres

- Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below.
- If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty).
- If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling, etc?

☐ Yes ☐ No If answer is "yes," type of consolidation \_\_\_\_\_

If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.) \_\_\_\_\_

No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Commission.



**CERTIFICATION**

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.

Name A. J. FORE

Position SUPERVISOR REG. & PERMITTING

Company SHELL WESTERN E&P INC.

Date 1-21-88

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my knowledge and belief.

Date Surveyed \_\_\_\_\_

Registered Professional Engineer and/or Land Surveyor \_\_\_\_\_

Certificate No. \_\_\_\_\_

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-7

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL ☒ GAS ☐ OTHER ☐  
2. Name of Operator  
SHELL WESTERN E&P INC.  
3. Address of Operator  
P.O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)  
4. Location of Well  
UNIT LETTER U 660 FEET FROM THE SOUTH LINE AND 660 FEET FROM  
THE WEST LINE, SECTION 2 TOWNSHIP 21-S RANGE 37-E N.M.P.M.

7. Unit Agreement Name  
8. Farm or Lease Name  
STATE SECTION 2  
9. Well No.  
3  
10. Field and Pool or Whichever  
DRINKARD/HARE SIMPSON  
BRUNSON ELLENBURGER

15. Elevation (Show whether DF, RT, GR, etc.)  
3467' DF  
12. County  
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPER. ☐ PLUG AND ABANDONMENT ☐  
PULL OR ALTER CASING ☐ OTHER ☒ CASING TEST AND CEMENT JOB ☐  
OTHER SQZ DRINKARD; ACDZ HARE SIMPSON & BRUNSON ELLENBURGER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. Set RBP @ 6900'. Dmp 2 sx sd on RBP.
3. Set cmt ret @ 6450'. Sqz Drinkard perfs 6562' - 6828' w/100 sx Cls "C" cmt + .3% Halad-9 followed by 50 sx Cls "C" cmt + 2% CaCl<sub>2</sub>. WOC 24 hrs.
4. DO cmt ret @ 6450' & cmt to sand cap on RBP.
5. Pres tst sqz to 500#.
6. Circ sand off RBP. Rel RBP & POH.
7. Acdz Ellenburger OH 7760' - 7906' w/8000 gals 15% HCl-NEA + 1500# rock salt.
8. Set RBP @ 7730'.
9. Acdz Hare Simpson perfs 7682' - 7697' w/4000 gals 15% HCl.
10. Rel RBP & POH.
11. Install prod equip & return well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 11-18-87

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

NOV 23 1987

APPROVED BY DATE TITLE DATE