

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06372
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT	
8. Well No.	322W
9. Pool name or Wildcat	NORTH EUNICE BLINEBRY-TUBB-DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Water Injector	
2. Name of Operator Shell Western E&P, Inc.	
3. Address of Operator P.O. Box 576, Houston, TX 77001 Shirley Galik - 5239 WCK	
4. Well Location Unit Letter S : 1980 Feet From The South Line and 1980 Feet From The West Line Section 2 Township 21S Range 37E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3488' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: AT, Drinkard Injector ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/24/95 To 4/29/95

POOH w/Inj Eqmt. Set Pkr @ 6742'. Reset Pkr @ 6654'. AT 6665-6824 w/2550 gals 20% HCL and 400# gelled rock salt as divert. Rel Pkr. Set RBP @ 6654 and Pkr @ 6596. AT Drinkard (6605-6643) w/840 gal 20% Hc. and 50# rock salt. Rel Pkr and retrieve RBP. Set Guiberson Uni VI Pkr @ 5728' and set Hyd Pkr @ 6860' PT csg to 500 PSI for 30 min. (Chart attached).
Return well to injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shirley G. Galik TITLE MGR - Reg. & Permitting DATE 7-9-95
TYPE OR PRINT NAME For: G. S. Nady TELEPHONE NO. 713/544-4219

(This space for State Use)


ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUL 17 1995

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUL 14 1995
JCD HOBBS
OFFICE

PRINTED IN U.S.A.



TEJAS
INSTRUMENT ENGINEERS

322 W

DATE TAKEN
TIME TAKEN
DATE TAKEN

DATE TAKEN
TIME TAKEN
DATE TAKEN

BR-2221
B 0-1000-8

NEDU

4-28-95

SHELL
NEDU #322W
30 MIN CHART @ 500#
GOLD STAR
UNIT #40
and 8 barrels

Shell Western E & P INC.
NEDA 322W
4-28-95

RECEIVED
JUL 14 1995
OCD HOBBS
OFFICE