

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name STATE SEC. 2
8. Well No. 14
9. Pool name or Wildcat HARE SIMPSON

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Shell Western E&P Inc.
3. Address of Operator P.O. Box 576 Houston, TX 77001-0576 (WCK 4587)	4. Well Location Unit Letter N : 3630 Feet From The SOUTH Line and 1770 Feet From The WEST Line Section 2 Township 21S Range 37E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3496' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: SI <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-08-92:

SI WELL. -- TO BE TA'D.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W. F. N. Kellendorf TITLE TECH. MANAGER - ENVIR. ENG. DATE 7/14/92

TYPE OR PRINT NAME W. F. N. KELLDORF

TELEPHONE NO. 713/870-3797

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

JUL 21 '92

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Shell Western E&P Inc.

3. Address of Operator

P.O. Box 576 Houston, TX 77001-0576

(WCK 4413)

8. Well No.

14

9. Pool name or Wildcat

HARE SIMPSON

4. Well Location

Unit Letter N : 3630 Feet From The SOUTH Line and 1770 Feet From The WEST Line

Section

2

Township

21S

Range

37E

NMPM

LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3496' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: DO CIBP, ACD & RTP ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-11 TO 10-21-91:

RIH W/7-5/8 IN. SWG TO 2600'. DIDN'T TOUCH ANYTHING. POH W/TOOLS. TAG TOC @ 7570'. DO CMT TO 7600'. DO CIBP, FELL FREE TO 7822'. DRLD TO 7917', COULD NOT MAKE FURTHER HOLE. ACD MCKEE/CONNELL PERFS 7642' - 7917' W/6300 GAL 15% NEFE HCL + 1500# ROCK SALT. INST PROD EQMT & RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

W. F. N. Kelldorf

TITLE DIV. ENVIRONMENTAL ENGR.

DATE 1/10/92

TYPE OR PRINT NAME

W. F. N. KELLDORF

TELEPHONE NO. 713/870-3426

(This space for State Use) ORIGINAL SIGNED BY JERRY BEXTON
DISTRICT I SUPERVISOR

JAN 14 '92

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name STATE SEC. 2
8. Well No. 14
9. Pool name or Wildcat HARE SIMPSON
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3496' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Shell Western E&P Inc.
3. Address of Operator P.O. Box 576 Houston, TX 77001-0576	4. Well Location Unit Letter N : 3630 Feet From The SOUTH Line and 1770 Feet From The WEST Line Section 2 Township 21S Range 37E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: FISHED TBG & TAC, SWGD & SI <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-07 TO 3-09-91:

ATTEMPTD TO CHNG OUT ROD PMP. PMP STUCK. BACKED RODS OFF & POH. REL TAC & ATTEMPTD TO POH W/ TBG. TAC HUNG UP 30' ABV SETTING DPT. WORKED TO REMOVE RODS TO BELOW TAC (LEFT 2 RODS & PMP IN TBG). STARTED OUT OF HOLE W/PROD STRING. TBG & TAC HUNG UP @ APPROX 2100. TBG WOULD MOVE DWN, BUT TAC WOULD NOT MOVE UP PAST 2100'. FP TBG & FOUND TBG STUCK @ 2186'. RIH W/TBG TILL TAC WAS @ 3025' & ATTEMPTD TO SET TAC, COULD NOT. RIH & SET TBG ON BTM. CUT TBG @ 7410' (41' ABV TAC). POH W/TBG. SWGD CSG W/4 IN., 4.5 IN. 5 IN. & 6 IN. TOOLS. RIH W/OS. LATCH ONTO FISH & POH W/14 JTS 2-3/8 IN. TBG, ANCHOR & MUD JT. SET RBP @ 3200' & DMPD 3 SX SD. SWGD THRU BAD CSG @ 2186'. PT TO 500#, HELD. RAN 7-3/4 IN. SWG THRU TI SPOT @ 2186', CSG HAD NOT COME BACK IN. RIH W/RETRVL HEAD. TAG @ 2906'. MADE 2' TO 2908' & STARTED GETTING 1.5 IN. CHUNKS OF CMT. PT CSG TO 500# & HELD 30 MIN. TAG @ 2906', HAD FILL TO 3013' & FELL OUT. RETAG @ 3220', HAD FILL TO 3240'. WSHD OUT 5' SD. RIH W/4.5 IN.

(CONT'D ON REVERSE SIDE)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. Smitherman TITLE REGULATORY SUPV. DATE 7/15/91
TYPE OR PRINT NAME J. H. SMITHERMAN TELEPHONE NO. 713/870-3797

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUL 22 1991

CONDITIONS OF APPROVAL, IF ANY:

Amended (see correction on backside)

HOBBS OFFICE
659

JUL 22 1991

RECEIVED

HOBBS OFFICE
659

JAN 13 1992

RECEIVED

magnet & tag @ 3245'. POH & retrvd 5 pcs metal. Tag @ 3244'. Wshd to top of BP. Latch
onto BP & POH w/tbg & RBP. Set CIBP @ 7600' (top perf @ 7647') & capped w/35' cmt. Circ'd
inhib fl. SI well. Eng eval collapsed csg.

7642

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Shell Western E&P Inc.

3. Address of Operator

P.O. Box 576 Houston, TX 77001-0576

8. Well No.

14

9. Pool name or Wildcat

HARE SIMPSON

4. Well Location

Unit Letter N : 3630 Feet From The SOUTH Line and 1770 Feet From The WEST Line

Section 2 Township 21S Range 37E NMPM LEA County

10. Elevation (Show whether DP, RKB, RT, GR, etc.)

3496' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: FISHED TBG & TAC, SWGD & SI ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-07 TO 3-09-91:

ATTEMPTD TO CHNG OUT ROD PMP. PMP STUCK. BACKED RODS OFF & POH. REL TAC & ATTEMPTD TO POH W/ TBG. TAC HUNG UP 30' ABV SETTING DPT. WORKED TO REMOVE RODS TO BELOW TAC (LEFT 2 RODS & PMP IN TBG). STARTED OUT OF HOLE W/PROD STRING. TBG & TAC HUNG UP @ APPROX 2100'. TBG WOULD MOVE DWN, BUT TAC WOULD NOT MOVE UP PAST 2100'. FP TBG & FOUND TBG STUCK @ 2186'. RIH W/TBG TILL TAC WAS @ 3025' & ATTEMPTD TO SET TAC, COULD NOT. RIH & SET TBG ON BTM. CUT TBG @ 7410' (41' ABV TAC). POH W/TBG. SWGD CSG W/4 IN., 4.5 IN. 5 IN. & 6 IN. TOOLS. RIH W/OS. LATCH ONTO FISH & POH W/14 JTS 2-3/8 IN. TBG, ANCHOR & MUD JT. SET RBP @ 3200' & DMPD 3 SX SD. SWGD THRU BAD CSG @ 2186'. PT TO 500#, HELD. RAN 7-3/4 IN. SWG THRU TI SPOT @ 2186', CSG HAD NOT COME BACK IN. RIH W/RETRVL HEAD. TAG @ 2906'. MADE 2' TO 2908' & STARTED GETTING 1.5 IN. CHUNKS OF CMT. PT CSG TO 500# & HELD 30 MIN. TAG @ 2906', HAD FILL TO 3013' & FELL OUT. RETAG @ 3220', HAD FILL TO 3240'. WSHD OUT 5' SD. RIH W/4.5 IN.

(CONT'D ON REVERSE SIDE)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. H. Smitherman

TITLE

REGULATORY SUPV.

DATE 7/15/91

TYPE OR PRINT NAME

J. H. SMITHERMAN

TELEPHONE NO. 713/870-3797

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

magnet & tag @ 3245'. POH & retrvd 5 pcs metal. Tag @ 3244'. Wshd to top of BP. Latch onto BP & POH w/tbg & RBP. Set CIBP @ 7600' (top perf @ 7647) & capped w/35' cmt. Circ'd inhib fl. SI well. Eng eval collapsed csg.

7647

RECEIVED

FILE