NEW MEXICO OIL CONSERVATION COMMISSION

SANTA FE, NEW MEXICO

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications commission advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed; and work should not begin until approval is obtained. See additional instructions in the Fules and regulations of the Commission.

OTICE OF INTENTION TO TEST CASING SHUT-OFF		x		INTENTION TO SHOOT	OR
NOTICE OF INTENTION TO CHANGE PLANS		ns		INTENTION TO PULL OF	R
NOTICE OF INTENTION TO REPAIR WELL		L	NOTICE OF	INTENTION TO PLUG W	/ELL
NOTICE OF INTENTION	TO DEEPEN WEI	LL			
		Hobbs,	New Mexico	May 8.	1952
OIL CONSERVATION CO	MMISSION,			_	
Gentlemen:					
Following is a notice of it	ntention to do certai	in work as de	scribed below at	the	
-				Well No. 4	
	21-S R		N. M. P. M.,	Undesignated	Field.
			,	-	
	FULL DETAI	IS OF DDO	DOCED DI AI	A OF MODE	
FOLLOW 1	NSTRUCTIONS IN	THE RULES	AND REGULAT	CIONS OF THE COMMISS	ION
Pon Kill engine	lines and seme				
MOME JO CHAINE.	エナいたす ないげ こたから	nted at 61	ll5 feet wit	h 500 sacks of 4% p	mal. 300 sacks
nam Je casing .	Timer and come	nted at 61	L15 feet wit	h 500 sacks of 4% g	el, 300 sacks
regular, and 75	sacks of Perl	ite. Top	of liner a	t 2999 . Plug down	5:10 PM 5-7-
regular, and 75	sacks of Perl	ite. Top	of liner a		5:10 PM 5-7-
regular, and 75	sacks of Perl	ite. Top	of liner a	t 2999 . Plug down	5:10 PM 5-7-
regular, and 75	sacks of Perl	ite. Top	of liner a	t 2999 . Plug down	5:10 PM 5-7-
regular, and 75	sacks of Perl	ite. Top	of liner a	t 2999 . Plug down	5:10 PM 5-7-
regular, and 75	sacks of Perl	ite. Top	of liner a	t 2999 . Plug down	5:10 PM 5-7-
regular, and 75	sacks of Perl	ite. Top	of liner a	t 2999 . Plug down	5:10 PM 5-7-
regular, and 75	sacks of Perl	ite. Top	of liner a	t 2999 . Plug down	5:10 PM 5-7-
regular, and 75	sacks of Perl	ite. Top	of liner a	t 2999 . Plug down	5:10 PM 5-7-
regular, and 75	sacks of Perlestimated 75 s	ite. Top	of liner a	t 2999 . Plug down	5:10 PM 5-7-
regular, and 75	sacks of Perlestimated 75 s	ite. Top	of liner a	t 2999 . Plug down	15:10 PM 5-7-
regular, and 75 Circulated out	sacks of Perl	ite. Top	of liner a	t 2999 . Plug down r WOC 48 hours will Shell Oil Compa	test casing.
regular, and 75 Circulated out	sacks of Perlestimated 75 s	ite. Top	of liner a	t 2999 . Plug down r WOC 48 hours will Shell Oil Compa	test casing.
regular, and 75 Circulated out	sacks of Perlestimated 75 s	ite. Top	of liner a	t 2999 . Plug down r WOC 48 hours will Shell Oil Compa	test casing. to Slag
regular, and 75 Circulated out	sacks of Perlestimated 75 s	ite. Top	ement. After a By	Shell O'l Compa Company or Oper L. E. Slagle	test casing. to Stage ator Callagator ical Engineer
regular, and 75 Circulated out	sacks of Perlestimated 75 s	ite. Top	By	Shell Oil Compacompany or Opers L. F. Slagle Division Mechan Send communications regar	test casing. to Stagnardical Engineer
regular, and 75 Circulated out	sacks of Perlestimated 75 s	ite. Top	By	Shell Oil Compared Company or Opers L. E. Slagle Division Mechan Send communications regar	test casing. Lest casing. Lest casing.