

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-73

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐  
Name of Operator  
Amoco Production Company  
Address of Operator  
P. O. Box 68 Hobbs, NM 88240  
Location of Well  
UNIT LETTER Q 660 FEET FROM THE East LINE AND 1980 FEET FROM THE South LINE, SECTION 4 TOWNSHIP 21-S RANGE 37-E

7. Unit Agreement Name  
8. Farm or Lease Name  
Southland Royalty "A"  
9. Well No.  
F 5  
10. Field and Pool, or Wildcat  
Blinebry-Drinkard DHC

15. Elevation (Show whether DF, RT, GR, etc.)  
3470 GL

12. County  
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|                                                           |                                           |                                                      |                                               |
|-----------------------------------------------------------|-------------------------------------------|------------------------------------------------------|-----------------------------------------------|
| PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>              | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/> |
| WELL OR ALTER CASING <input type="checkbox"/>             | OTHER <input type="checkbox"/>            | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | OTHER <input type="checkbox"/>                |

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to clean out fill and open additional pay then acidize all perfs. MIRU-SU. POH w/prod. equip. Kill well. Clean out wellbore to 6700'. Top of fill is 6608 and there are two bit cones at 6665. Use a bulldog bailer or foam unit. Run GR/CC1/CNL log from 6700'-4700'. Perforate 6690-96, 6678-86, 5702-10', 5668-78', 5650-54, 5610-16 w/4 JSPF and 120° or 90° phasing 3-1/8" gun. RIH w/PPIP set to 2 ft spacing. Acidize the perfs mentioned above w/100 gal of 15% HCl per foot of perfs. 4200 gals total. Add 2 gal/1000 of WA-212, 2 gal/1000 of WA-211, 10 gal/1000 of citric acid and 10 gal/1000 of acetic acid. RIH w/packer and 3000 gal gelled acid. Move packer and RBP to 5500' and 6100' resp. Pump 500 gal xylene followed by 5000 gal of gelled acid. POH x install producing equip. RD-MOSU

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

by Paul Kautz TITLE Admin. Analyst DATE 2-9-87  
Orig. Signed by  
Paul Kautz  
Geologist  
COPIES OF APPROVAL, IF ANY: TITLE DATE FEB 11 1987

RECEIVED

FEB 10 1987

OCD  
HOBBS OFFICE