

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL WELL ☒ CAR WELL ☐ OTHER ☐	7. Unit Agreement Name NORTHEAST DRINKARD UNIT
2. Name of Operator SHELL WESTERN E&P INC. (4431 WCK)	8. Farm or Lease Name NORTHEAST DRINKARD UNIT
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001	9. Well No. 203
4. Location of Well UNIT LETTER P 3200 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 4 TOWNSHIP 21-S RANGE 37-E N.M.P.M.	10. Field and Pool, or Wildcat NORTH EUNICE BLINEBRY-TUBB-DRINKARD OIL & GAS
15. Elevation (Show whether DF, RT, GR, etc.) 3474' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPER. ☐
CASING TEST AND CEMENT JOB ☐
OTHER SQZ, PERF, SAND FRAC, AT ☒

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-11-88 to 2-8-88:

POOH w/ prod equip. Sqz Drinkard perfs 6572' - 6692' w/ 100 sxs class "C" cmt + .3% Halad-9 followed by 50 sxs class "C" + 2% CaCl₂ and Blinebry perfs 5552' - 6000' w/ 100 sxs class "C" cmt + .3% Halad-9 followed by 100 sxs class "C" cmt + 2% CaCl using BP's and pkr's. DO and CO to 6870'. Perf Drinkard 6690' - 6784' w/ 1 JSPF. Run Base/GR log from PBDT @ 6865' to 6350'. AT Drinkard 6690' - 6784' w/ 630 gals 15% NEFE HCl acid. Sand frac Drinkard perfs 6690' - 6784' w/ 12,600 gals x-linked 40# gel + 54,000# 20/40 sand. CO to PBDT @ 6870'. Run GR Survey from PBDT to 6350'. RIH w/ prod equip and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.F.N. Kelldorf WFN KELLDORF TITLE STAFF PRODUCTION ENGINEER

DATE 11/2/88

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

NOV 7 1988

OCD
HOBBS OFFICE