

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator W. K. Byrom		8. Farm or Lease Name Gulf Hill
3. Address of Operator Box 147 - Hobbs, N. M. 88240		9. Well No. 2
4. Location of Well UNIT LETTER <u>N</u> , <u>1980</u> FEET FROM THE <u>W</u> LINE AND <u>3300</u> FEET FROM THE <u>S</u> LINE, SECTION <u>4</u> TOWNSHIP <u>21</u> RANGE <u>37</u> NMPM.		10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3477 GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-20-76: Ran CIBP at 4503 and dumped 35' cement on top of plug. Ran cement bond log and compensation Neutron log. Perforated at 4174, 4183, and 4192 with 2 shot 1 int, ran tbg and packer acidized with 1500 gal NE acid at 3 bpm and 2000 psi. Pulled swab 3 times and well started flowing 20 bbls hr water which is about 3% oil/. Killed well with brine water and set CIBP at 4120 dumped 35' of cement on top of plug. Perforated at 3090, 3928, 3936, 3951, 3968, 3972, 4001, 4010 and 4019 with 2 shots/ int. Ran tbg and acidized with 2000 gal 15% NE acid at 3.4 bpm and 2200 psi. Started swabbing, getting show of oil and gas. Fraced this zone with 42,000 gal 2% KCL water and 30,000# sand at 28 bpm and 2200 psi. Put well on pump getting 10 bbl oil plus 1 bbl water.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W. K. Byrom</u>	TITLE <u>Geologist</u>	DATE <u>4-5-76</u>
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		