

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	X	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

October 12, 1954
(Date)

Hobbs, New Mexico
(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

F. J. Danglade
(Company or Operator)

Alexander
(Lease)

La Mance Drilling Company, Well No. 1 in the SW 1/4 NW 1/4 of Sec. 7,
(Contractor)

T. 21S, R. 37E, NMPM, Eumont Pool, Lea County.

The Dates of this work were as follows: 10-8-54 and 10-10-54

Notice of intention to do the work (was) (~~was~~) submitted on Form C-102 on _____, 19____,
(Cross out incorrect words)

and approval of the proposed plan (was) (~~was~~) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Ran 3,428' 5 1/2" - 14#, J-55 new casing. Cemented at 3,435' using two stage cementing tool at 1,348'. Used 200 sax cement at bottom and 100 sax at 1,348'. After cement set 36 hours, applied 1000# pressure. Held for 15 minutes.

Witnessed by W. W. LaMance La Mance Drilling Company, Supt.
(Name) (Company) (Title)

Approved: OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name J. H. Moore

Position Geologist

Representing F. J. Danglade

Address Box 1537, Hobbs, New Mexico

(Title)

(Date)