

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different horizon. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P.O. Box 40, Hobbs, N.M. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. Use space below.)
AT SURFACE: 1980' FSL & 1980' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☒

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(Other) DHC ☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drill out pkr at 6500'. CD to 6735'. Set pkr at 6450'. Acidize Drinkard as follows: Pump 130 bbls. 15% HCL-NE-FE in 3 stages. Divert between stages w/ total of 1400# 50% rock salt & 50% Benzoic flakes in 933 gals. 10ppg brine. Flush w/ 65 bbls. 2% KCL wtr. Swab. Set RBP at 6050', pkr. at 5500'. Acidize Blinebry as follows: Pump 16 bbls. 15% HCL-NE-FE. Flush w/ 60 bbls. 2% KCL wtr. Swab. Run production equipment. Test.

DHC approved under Administrative Order No. DHC-332.

Subsurface Safety Valve: Manul. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *Wm A. Gillham* Administrative Supervisor DATE *March 30, 1981*

(This space for Federal or State office use)

APPROVED (Orig. Sgd.) *PETER W. CHESTER* TITLE DATE

CONDITIONS OF APPROVAL, IF ANY

JAMES A. GILLHAM
DISTRICT SUPERVISOR

See Instructions on Reverse Side

5. LEASE *NM-2512*
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME *NMFL*
8. FARM OR LEASE NAME *Hawk B-1*
9. WELL NO. *2*
10. FIELD OR WILDCAT NAME *Blinebry Oil & Gas / Drinkard*
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA *Sec. 9, T-21S, R-37E*
12. COUNTY OR PARISH *Lea* 13. STATE *NM*
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

USGS 5
NMRL 4
FILE