

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

HOBBS OFFICE N.M.C.C.  
Mar 1 3 28 PM '66

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator <b>Aztec Oil &amp; Gas Company</b>	5. State Oil & Gas Lease No.
3. Address of Operator <b>P. O. Box 837, Hobbs, New Mexico</b>	7. Unit Agreement Name
4. Location of Well UNIT LETTER <b>A</b> <b>330</b> FEET FROM THE <b>North</b> LINE AND <b>990</b> FEET FROM THE <b>East</b> LINE, SECTION <b>10</b> TOWNSHIP <b>21-S</b> RANGE <b>37-E</b> NMPM.	8. Farm or Lease Name <b>Duiron</b>
	9. Well No. <b>3</b>
	10. Field and Pool, or Wildcat <b>Wantz Abo</b>
11. Elevation (Show whether DF, RT, GR, etc.) <b>3430 D.F.</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER _____		OTHER <b>Plugged back from Hare-Simpson to the Wantz Abo.</b> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**This well was completed in the following manner:**

1. Killed Hare-Simpson zone with fresh water, pulled tubing, and logged from FBTD to 5000'.
2. Perforated with 4-Way Jet at 7390' and 7102'.
3. Set C.I.B.P. at 7420 and capped with cement.
4. Attempted to squeeze at 7377 and 7110, but couldn't pump into after spotting acid.
5. Perforated Wantz Abo at 6847, 49, 51, 53, 79, 81, 83, 6920, 22, 41, 43, 85, 87, 94, 96, 7005, 07, 11, 13, 7143, 45, 75, 77, 7213, 15, 35, 37, 55, 57, 82, 84, 7310, 13, 59, 61, 63, 75, 77.
6. Acidized with 500 gallons 15% H.E., 2000 gallons Unisol, and 12,000 gallons B.J. Service SRA III with 50 rubber ball sealers.
7. Well flowed 92 BOPD and no water on 2/28/66.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <b>original signed by: LESTER DUKE</b>	TITLE <b>District Superintendent</b>	DATE <b>March 1, 1966</b>
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

3 50 PM '82