

NM-2512

5. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

MAR 12 11:05 AM '90

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

SHELL WESTERN E&P INC. (4435 WCK)

CARLSBAD, N.M.
AREA

3. ADDRESS OF OPERATOR

P. O. BOX 576, HOUSTON, TEXAS 77001

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FNL & 1980' FEL SEC. 10

unit B

14. XXXXXX API #
30-025-06450

15. ELEVATIONS (Show whether OF, AT, GR, etc.)

3436' GR

7. UNIT AGREEMENT NAME

NORTH-EAST DRINKARD UNIT

8. FARM OR LEASE NAME

NORTH-EAST DRINKARD UNIT

9. WELL NO.

405

10. FIELD AND POOL, OR WILDCAT
NORTH EUNICE-BLINEBRY-TUE
DRINKARD OIL & GAS11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC 10, T 21-S, R 37-E

12. COUNTY OR PARISH 13. STATE

LEA

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Abandon exst Tub/Pk; recomp as GW

(Note: Report results of Multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11-09 to 11-28-89:

POH w/prod equip. CO to 6540' (tagged fill). Set CIRP's @ 6538' & 6160'. Capped each BP w/35' cmt. Pres tstd csg to 500# for 15 min, held OK. TIH w/prod string consisting of WL entry guide, Baker Lok-set PKR & 2-7/8" tbg. Spotted acid from 5680' to 5570'. Set pkr @ 5482'. Pres tstd pkr & csg to 500# for 30 min, held OK. Perf'd Blinebry 5584' - 5670' (1 JSPF). RU CO₂. Pres tstd backside to 500#. Began foam acid treatment. w/2.5 tons CO₂ and 546 gals 20% HCl pmpd, backside comm. Susp treatment immed. Rel pkr & POH. Upon insp of pkr, found bypass O-rings damaged. RIH w/Baker Lok-set PKR on 2-7/8" tbg. Pmpd inhib fl. Set pkr @ 5482'. Inst WH. Ran static BHP. Acid Blinebry perfs 5584' - 5670' w/2473 gals 20% HCl + 30 tons CO₂. Flwd to pit thru 18/62" chk. Flwd well 4 hrs & turned to satellite.

11-29 to 11-30-89:

Well died. SI well 24 hrs. Opnd well to pit, flwd 30 min & died.

12-04 to 12-05-89:

Rel pkr @ 5482' & POH. Inst prod equip & WH. Retd to prod.

ACCEPTED FOR RECORD

MAR 14 1990

RECEIVED

JAN 12 12 20 PM '90

18. I hereby certify that the foregoing is true and correct

J. H. SMITHERMAN TITLE REGULATORY SUPV.

DATE 1-08-90

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED

MAR 19 1999

OCD
HOBBS OFFICE