

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other: Instruct
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-025124

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME NMFU
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Hawk B-10
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. 4
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNK & 660' FEL - Unit Letter H	10. FIELD AND POOL, OR WILDCAT Blindary O & Gas want also
14. PERMIT NO. 30-025-06453	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
12. COUNTY OR PARISH Lea	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) Connect to Useable Wellbore	
(Other) ☐		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started on 11-19-87. MIRR. Check for paraffin. POOH w/ rods & pump. Kill well w/ 28 bbls 9# brine w/ Adomall. Run bit & scraper to 6680'. POOH. Tag model D pkr at 6680'. Pull up 4' & set CIBP at 6676 to shut off also. POOH. Set 5 1/2" model "R" pkr at 6100'. Load Hg w/ 28 bbls 9# brine w/ Adomall & pressure test CIBP to 500 psi. Release pkr & POOH. Go in hole w/ 2 1/8" production Hg string & land. Rig down on 11-24-87.

ACCEPTED FOR RECORD

JAN 22 1988

SJS
CARLSBAD, NEW MEXICO

RECEIVED
DEC 23 12 13 PM '87
CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* J. FINNEY

TITLE Administrative Supervisor

DATE December 22, 1987

This space for Federal or State office use)

APPROVAL OF
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See instructions on Reverse Side

Under 18 U.S.C. section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) ARCO (2) Amoco (2) Chevron (1) File 24.abr of 12/87