

(November 1983)
(Formerly 9-331)

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

P.O. BOX 1980

HOBBS, NEW MEXICO

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-0317b NM 2512

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

SHELL WESTERN E&P INC.

3. ADDRESS OF OPERATOR

P.O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface 1980' FNL & 2310' FEL SEC. 10

7. UNIT AGREEMENT NAME

NORTHEAST DRINKARD UNIT

8. FARM OR LEASE NAME

NORTHEAST DRINKARD UNIT

9. WELL NO.

407

10. FIELD AND POOL, OR WILDCAT
NORTH EUNICE BLINEBRY-
TUBB-DRINKARD OIL & GAS

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 10, T21S, R37E

14. XXXXXX API NO.

30-025-06456

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3451' DF

12. COUNTY OR PARISH

LEA

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) CMT SQZ BLINEBRY; LOG

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. POH w/prod equip.
2. Set RBP @ 6200' & cap w/2 sx sd.
3. Set pkr @ 5600'.
4. Sqz Blinebry perfs 5726' - 6032' w/50 sx CIs "C" cmt + .3% D-60 followed by 50 sx CIs "C" cmt + 2% CaCl₂. POH w/pkr. WOC 24 hrs.
5. DO cmt to 6050'. Pres tst sqz to 500#. CO to sd cap on RBP.
6. Circ sd off RBP & retrieve.
7. Run SDT, CNL, GST, NGT, CET/CBL logs.
8. Perf Tubb 6073' - 6145'.
9. Set RBP @ 6450'.
10. Acdz perfs 6073' - 6145' w/4200 gals 15% HCl-NEA.
11. Install prod equip & return well to prod to zone tst Tubb.
12. POH w/prod equip & RBP.
13. Perf Blinebry/Tubb/Drinkard 5802' - 6752'.
14. Acdz perfs 5802' - 6752' w/15,750 gals 15% HCl-NEA + 2000# rock salt using RBP & pkr.
15. POH w/RBP & pkr.
16. Install prod equip & return well to prod. *see amended C-103*

18. I hereby certify that the foregoing is true and correct

SIGNED

W.F.N. KELLDORF

W.F.N. KELLDORF

TITLE STAFF PRODUCTION ENGINEER

DATE 5-05-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

5-13-88

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RECEIVED

MAY 16 1988

CCO
HOLDS OFFICE