

NO. OF COPIES RECEIVED		
DISTRIBUTION		
ANTA FE		
ILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. B-11349		
7. Unit Agreement Name		
8. Farm or Lease Name State 10		
9. Well No. 1		
10. Field and Pool, or Wildcat Wantz Abo		
11. Elevation (Show whether DF, RT, GR, etc.)		
12. County Lea		

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☐ CHANGE PLANS ☐ OTHER ☐
REMEDIAL WORK ☒ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOB ☐ OTHER D.O. pkr & stimulate ☐ ALTERING CASING ☐ PLUG AND ABANDONMENT ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU 3-22-83. Cut over pkr @ 6690'. Cut over junk @ 7542'. Cut over fish to 7551'. Wash over fish to 7670'. Recover 3 small pieces of tbg. Set RBP @ 7148'. Set pkr @ 6794'. Acidize Abo w/ 60 BBL 15% HCL-NE-FE acid. Divert w/ 150# rocksalt & 150# benzoic acid. flakes. Flush w/ 40 BBL TFW. Swbd. Rel pkr. & RBP. Set RBP @ 6008'. Set pkr. @ 5510'. Acidize Blinebry w/ 16 BBL 15% HCL-NE-FE acid. Swbd. Rel pkr. & RBP. Ran production equipment. Test.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Greg Perry</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>4-27-83</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		
REMOVED BY	TITLE	DATE <u>APR 29 1983</u>
CONDITIONS OF APPROVAL, IF ANY:		