



# CONTINENTAL OIL COMPANY

P. O. Box 68  
Eunice, New Mexico  
April 10, 1962

Mr. Joe Ramey  
New Mexico Oil Conservation Commission  
P. O. Box 2045  
Hobbs, New Mexico

Dear Sir:

This statement is made in explanation of the recorded pressures on the Blinebry side of the attached packer leakage test on Continental Oil Company's State 10 No. 1 conducted March 14 thru March 18, 1962.

At the start of the test, two 2,000 lb. Bourdon elements were installed in the recorder. It now appears, at the conclusion of the test, that the main connection to the recorder pen, used on the Blinebry side, was incorrectly adjusted and the pressures, as traced by this arm, cannot be read directly from the chart. All pressures recorded are relative and indicate no communication between zones. The numerical value of pressures indicated on the chart were measured with a dead weight tester.

If further explanation of pressure behavior during these tests is desired, please do not hesitate to contact this office.

Yours very truly,

J. R. PARKER  
District Superintendent

JRP-BFH

Attachment