

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
B-935	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name
2. Name of Operator		NORTHEAST DRINKARD UNIT
3. Address of Operator		8. Farm or Lease Name
P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)		NORTHEAST DRINKARD UNIT
4. Location of Well		9. Well No.
UNIT LETTER <u>N</u> <u>500</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>1880</u> FEET FROM		10. Field and Pool, or Wildcat
THE <u>WEST</u> LINE, SECTION <u>10</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> N.M.P.M.		NORTH EUNICE BLINEBRY-TUBB-DRINKARD OIL & GAS
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3455' GR		LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER <u>Cmt sqzd, log, OAP & Acd</u> ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1403.

9-20 to 9-30-88:

POH w/prod equip. Set pkr @ 5660'. Sqzd Blinebry perms 5788' - 5818' w/50 sx CIs "C" cmt + .03% Hald-9 followed by 25 sx CIs "C" cmt + 2% CaCl₂. POH w/pkr. DO cmt 5660' - 5753'. Pres tstd sqz to 500#, held OK. DO CIBP @ 6050' & CO to 6350'. Set pkr @ 6000'. Sqzd Tubb perms 6105' - 6359' w/125 sx CIs "C" cmt + .03% Hald-9 followed by 25 sx CIs "C" cmt + 2% CaCl₂. POH w/pkr. DO cmt 6042' - 6311'. Pres tstd csg to 700#, did not hold. DO CIBP @ 6360', pushed remains below 6926'. Reamed 6926' - 95' & circ'd clean. Set CIBP @ 6900'. Ran GR/CNL/CCL from 6250' - 5550'. Perf'd Blinebry/Tubb/Drinkard 5729' - 6784' (1 JSPE). Capped CIBP @ 6900' w/35' cmt. Acd perms 5729' - 6784' w/9450 gals 15% HCl-NEFE in 3 stages. Tagged PBTD @ 6871'. Installed prod equip & retd well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER DATE 2-27-89

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

MAR 2 1989

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 1 1989

OCD
HOBBS OFFICE