

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-935
7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
8. Well No. 501
9. Pool name or Wildcat NORTH EUNICE BLINEBRY-TUBB- DRINKARD OIL & GAS

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator SHELL WESTERN E&P INC.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	4. Well Location Unit Letter <u>L</u> : <u>1980</u> Feet From The <u>SOUTH</u> Line and <u>330</u> Feet From The <u>WEST</u> Line Section <u>10</u> Township <u>21S</u> Range <u>37E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3470' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>TA'd</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-01 to 7-07-89:

CO to PBTD (5929'). 106 jts 1-5/8" workstring dropped 12' into 2-7/8" csg while POH. Attemptd to free fish, could not. Cut 2-7/8" csg 40' from surf. Install 2-7/8" L-80 sub to csg top. Work csg free. POH w/1-1/2 jts 2-1/2" pipe, x-over, 7' X 2-7/8" J-55 sub, & 1-5/8" tbg. POH w/remaining workstring. Set CIBP @ 5610' & capped w/cmt. Back csg off 1 jt below cut. POH w/tools & 1/2 jt csg w/collar. RIH w/4' x-over sub, 3' sub, 31' X 2-7/8" tbg, 2-10' subs, & 1-4' sub (all subs 2-7/8" EUE BRD J-55 pipe). Screw into csg. Tagged TOC @ 5573'. Circ'd inhib wtr. Pres tstd csg to 500# for 30 min, held OK. Well is TA'd.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 8-4-89
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY DIXON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 8 1989
CONDITIONS OF APPROVAL, IF ANY:

TA'd 8-1-90

RECEIVED

AUG 7 1989

OCD
HONORS OFFICE