

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

DATE
LEASE DESIGNATION AND SERIAL NO.
LC-032096B
IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER <u>Dual</u>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR <u>Conoco Inc.</u>	8. FARM OR LEASE NAME <u>Lockhart B-11</u>
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, NM 88240</u>	9. WELL NO. <u>#2</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>330' FNL & 330' FWL</u>	10. FIELD AND POOL, OR WILDCAT <u>Blinbury 046, Drinkard</u>
14. PERMIT NO. <u>30-025-06477</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>11-215-37E</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACTURE TREAT	☒	FRACTURE TREATMENT	☐
SHOOT OR ACIDIZE	☒	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	REPAIRING WELL	☐
(Other)	☐	ALTERING CASING	☐
PULL OR ALTER CASING	☐	ABANDONMENT*	☐
MULTIPLE COMPLETE	☐		
ABANDON*	☐		
CHANGE PLANS	☐		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The purpose of this procedure is to clean-out, reperf & acidize the Drinkard, perforate Blinbury zones 4 + 5 and sand frac the Blinbury as follows:

1. POOH w/ rods & tubing
2. GIH w/ 4-3/4" bit and clean out fill above Model D packer
3. Mill out Model D packer @ 6196'. POOH w/ packer & tailpipe
4. GIH w/ 4-3/4" bit. Drill out CIBPs @ 6660 and 6711' and circ. hole clean
5. Reperf lower Drinkard
6. Acidize Drinkard & test
7. Perforate Blinbury zones 4 and 5
8. Sand frac Blinbury
9. GIH w/ tubing, pump and rods and test pump.

ACCEPTED FOR RECORD
A.S.
APR 18 1990

LEA COUNTY, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED H.A. Ingram TITLE Conservation Coordinator DATE 4/19/90

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____

*See Instructions on Reverse Side