## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

44, 00 COPIES PLEETINGS	T	
DISTRIBUTION	7	
BANTA FE	1	
FILE		
U.3.0.5.	T	
LAND OFFICE		
OPERATOR		

## OIL CONSERVATION DIVISION P. O. BOX 2088

SANTA FE, NEW MEXICO 87501	Revised 10-7-		
U.S.O.S.	Sa. Indicate Type of Lease		
LAND OFFICE	State X Fee		
OPERATOR	5. State Oti & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS			
(BO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
I.  OIL X GAB OTHER-	7. Unit Agreement Name		
2. Name of Operator	8. Farm or Lease Hame		
SHELL WESTERN E&P INC.  J. Address of Operator	STATE SECTION 2*		
P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	20*		
UNIT LETTER V , 990 FEET FROM THE SOUTH LINE AND 2300 FEET FROM	10. Field and Pool, or Widcat BLINEBRY		
THE WEST LINE, SECTION 2 TOWNSHIP 21-S RANGE 37-E NAPM.			
15. Elevation (Show whether DF, RT, GR, etc.) 3477 DF	12. County LEA		
Check Appropriate Box To Indicate Nature of Notice, Report or Oth			
	REPORT OF:		
PERFORM REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON COMMENCE DRILLING OFMS.	PLUG AND ABANDONMENT		
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQS			
SQZ, PERF & ACDZ			
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. *NEW WELL NAME: NORTHEAST DRINKARD UNIT #31	estimated date of starting any proposes .7		
1. POH w/prod equip. 2. Set pkr @ 5600' & estab inj rate.			
3. Sqz Blinebry perfs 5672' - 5893' w/100 sx Cls "C" cmt + .3% Halad-9	followed by 50 sx Cls		
. CHU + 2% (3) 10 WOL 2/L NYC			
4. TOH w/pkr. DO cmt to 5910'. Pres tst sqz to 500# @ 5750', 5850' & 5- Perf Blinebry 5857' - 5905' (1 JSPF).	5910'.		
5. Run base GR/Temp log from PBTD to 5500'.			
6. Acdz perfs 5857' - 5905' w/2000 gals 15% HCl-NEA + 250# rock salt.			
7. Run base GR/Temp log from PBTD to 5500'. 8. Flow back on 8/64" choke until well dies.			
<ol> <li>Flow back on 8/64" choke until well dies.</li> <li>Install prod equip &amp; return well to prod.</li> </ol>			
in the production of the court were to product the court were the court			
	*		
и́.			
8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
A. J. FORE TITLE SUPERVISOR REG. & PERMITTING	DATE 12-8-87		
ORIGINAL SIGNED BY JERRY SEXTON			
ORIGINAL SIGNED BY SERVISOR  DISTRICT I SUPERVISOR			

## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

(			
DISTRIBUTION	1		
BANTA FE			
FILE			
U.S.G.S.	1		
LANG OFFICE			
CREATOR	1		

## OIL CONSERVATION DIVISION

DISTRIBUTION SANTA FE	1	. BOX 2088		Form C-103 Revised 10-1-?	
7168	SANTA FE, I	NEW MEXICO 87	501	NC 7	1966 10-1-3
U.S.G.S.	•			Sa. Indicate Type of Lea	5.0
LAND OFFICE				State X	Fee 🗌
GPERATOR				5. State Oil & Gas Lease	No.
(DO NOT USE THIS FORM FOR PRC	Y NOTICES AND REPORTS				
USC "APPLICATI	ION FOR PERMIT -" (FORM C-10) 1 FO	OR SUCH PROPOSALS.)	T MESERVOIR.	7777777777	777777
CIL X WELL				7. Unit Agreement Name	
week [A] welk [	OTHER-				
,				6. Farm or Lease Hame	•
SHELL WESTERN E&P INC.				STATE SECTION	2
	TV 77001				
P. O. BOX 991, HOUSTON	, IX //UU1	·		20 10. Field and Pool, or W.	11 d
UNIT LETTER V	990 FEET FROM THE SC	UTH LINE AND	2300	BLINEBRY	nacci
THE WEST LINE, SECTIO	эн2 томнянія	21-S RANGE	37-E NAPM.		
	15. Elevation (Show wh	ether DF, RT, GR, etc.		12. County	4444
	3477' DF			LEA (	
Check	Appropriate Box To Indica	ite Nature of Notic	e. Report of Othe	er Data	<del>**</del>
	TENTION TO:		SUBSEQUENT		
PERPORM REMEDIAL WORK	PLUC AND ABANDON		. [7]		_
Truesta trace	PEUE AND ABANDON			ALTERING CAS	<u></u>
PULL OR ALTER CASING	EHANGE PLANS	CASING TEST AND	<del></del>	PEUG AND ASAN	DONNENT [
		OTHER	_		Γ-
OTHER					L.
				···	
<ol> <li>Describe Proposed or Completed Op work/ SEE RULE 1103.</li> </ol>	erations (Clearly state all pertine	nt details, and give pert	inent dates, including e	estimated date of starting	any propose:
4-15-85: Tagged btm @ RBP @ 5600'.	5895'. Btm 20 jts t Located hole in csg				Set
4-16-85: Circ'd hole retainer 0 4	w/fresh wtr. Pulled 753'. Sliding valve		· .	and on RBP. Set	cmt
	ng to jar valve open ot recover fish. Set sx Class "C" cmt.	no success. pkr @ 3808'.	Rotated 4-11/1 Cmt'd csg leak	16" tapered shoe k between 4914'	over -
4-22-85: Tagged TOC @ to 1000 psi,		to 4972'. Circ	c'd hole clean.	. Pressure test	ed csg
4-23-85: Circ'd junk cover fish. Pulled RBP @	Circ'd hole & jarred				
	00# rock salt. Instal	led production	equipment & re		
8. I hereby certify that the information	above is true and complete to the	best of my knowledge a	nd belief.		
This Curtific	A. J. FORE	SUPERVISOR REG	. & PERMITTING	JUNE 19,	1985
June June	TIVLE			PATE	

ORIGINAL SIGNED BY EDDIE SEAY

JUN 2 4 1985

Production of the second

JUN 21 1985

HONE STATE