I

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

2000					
أَوِلَ فَتِ الْ	MY	9	$f_{i:I}^{i:i}$	1)	03

	1.8		12-31-60. Tuco	
Land Office				
Lease No	LC	03	1741	þ
Unit	NXI	U		

Budget Bureau No. 42-R358.4.

					
NOTICE OF IN	TENTION TO DRILL	SUBSEQUE	IT REPORT OF WATER SH	UT-OFF	L.A.
NOTICE OF IN	TENTION TO CHANGE PLANS	SUBSEQUEN	T REPORT OF SHOOTING	OR ACIDIZING	
NOTICE OF IN	TENTION TO TEST WATER SHUT-OFF	SUBSEQUEN	T REPORT OF ALTERING	CASING	
NOTICE OF IN	TENTION TO RE-DRILL OR REPAIR WEL	L SUBSEQUEN	T REPORT OF RE-DRILLIN	NG OR REPAIR	
NOTICE OF IN	TENTION TO SHOOT OR ACIDIZE	SUBSEQUEN	T REPORT OF ABANDONM	ENT	
NOTICE OF IN	TENTION TO PULL OR ALTER CASING		TARY WELL HISTORY		
NOTICE OF IN	TENTION TO ABANDON WELL				
	(INDICATE ABOVE BY CH	IECK MARK NATURE OF REPO	RT, NOTICE, OR OTHER DA	TA)	
Hawk B	-3	***************************************	3 ¢	lay 8	, 19
	-TB is located 1980	ft. from N line an	d 1980 ft. from	$\left\{ \begin{array}{c} E \\ \bullet \end{array} \right\}$ line of s	sec. 3
3/4 Je	c 3 21 and Sec. No.) (Twp.)	3 37 t. (Range)	2174		
	Blinebry	LGM	(Meridian)	. 85 a 3	
· · · · · · · · · · · · · · · · · · ·	Field)	(County or Subdivision)		ate or Territory)	
	and expected depths to objective sands ing points	, and an other important pr	ngths of proposed casing: oposed work)		
	and expected depths to objective sands	s; show sizes, weights, and le s, and all other important pr	ngths of proposed casing: oposed work)		
	and expected depths to objective sands ing points	s; show sizes, weights, and le s, and all other important pr	ngths of proposed casing: oposed work)		
	and expected depths to objective sands ing points	s; show sizes, weights, and le s, and all other important pr	ngths of proposed casing: oposed work)		
	and expected depths to objective sands ing points	s; show sizes, weights, and le s, and all other important pr	ngths of proposed casing: oposed work)		
Ran g down ore dr	187 joints 5 1/2" 4-30-57. Top of 111ing plug 1600-1	c; show sizes, weights, and let, and all other important process and all other important process and all other important process and all other important process.	ngths of proposed casing oposed work) 5974' with Thirty min i plug to 59	400 sack ute casi 170'.	s cemei
Ran down ore dr.	and expected depths to objective sands ing points	c; show sizes, weights, and let, and all other important processing set at coment 3000.	ngths of proposed casing oposed work) 5974' with Thirty min i plug to 59	400 sack ute casi 170'.	s cemei
an g down ore dr.	and expected depths to objective sands ing points 187 joints 5 1/2" 4-30-57. Top of illing plug 1600-1	c; show sizes, weights, and let, and all other important processing set at coment 3000.	ngths of proposed casing oposed work) 5974' with Thirty min i plug to 59	400 sack ute casi 170'.	s cemei
g down ore dr.	and expected depths to objective sands ing points 187 joints 5 1/2" 4-30-57. Top of a company plus 1000-10 that this plan of work must receive ap Continental Cil Co	c; show sizes, weights, and let, and all other important process of the constant 3000. Casing Set at coment 3000. Drille	ngths of proposed casing oposed work) 5974' with Thirty min i plug to 59	WU SACK	S COME